Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resource	Form C-103 ces March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-38062
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III Santa Fa NM 97505	STATE FEE
District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU	·
TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 SUCH PROPOSALS.)	1) FOR NORTHEAST DRINKARD UNIT 8. Well Number
1. Type of Well:	o. Well Number
Oil Well Gas Well Other 2. Name of Operator	245
APACHE CORPORATION	9. OGRID Number 873
3. Address of Operator	10. Pool name or Wildcat
6120 S. YALE, STE. 1500 TULSA, OK 74136	EUNICE; BLI-TU-DR, NORTH 22900
4. Well Location	
Unit Letter I : 2310 feet from the S line and 430 feet from the E line Section 2 Township 21S Range 37E NMPM County: LEA	
Section 2 Township 21S Range 37E NMPM County: LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3,494	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: ULSectTwpRngPit typeDepth to Grou	
Distance from nearest surface water Below-grade Tank Location ULSect	TwpRng
feet from theline andfeet from theline	A SOCO
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDI	AL WORK ALTERING CASING
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMME	NCE DRILLING OPNS.□ PLUG AND □
PULL OR ALTER CASING MULTIPLE CASING	ABANDONMENT TEST AND
COMPLETION CASING COMPLETION	
OTHER:	ODUD OUDS OOD TO LOO TO LOO
	SPUD, SURF. CSG., TD, LOG, PROD. CSG.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
ROBB 1103. Tot Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
08/30/06 SPUD	
08/31/06 CASING STRING @ 1,290, HOLE SIZE 12.25, STRING SIZE 8.625, TYPE J-55, WEIGHT 24.0, 600 SACKS OF SEMENT, CLASS C,	
CIRCULATE TO SURFACE	
09/09/06 DRILL F/ 7139' TO 7155'. CIRCULATE & CONDITION HOLE F/ E-LOGS. I	DROP SURVEY @ 7103' F/ 1 DEG.; TOH: LD BHA.
RU HLS & LOG WELL; DLL/MSFL/SONIC/GR F/ 7152' - 4000'; DUAL-SPACED NEUTRON/SPECTRAL DENSITY/CALIPER; F/ 7155 - 200'.	
09/09/06 SET PROD. CASING @ 7,155', HOLE SIZE 7.875, STRING SIZE 5.5, TYPE L-80/J-55, WEIGHT 17.0, 1,400 SACKS OF CEMENT, CLASS C, CIRCULATE TO SURFACE. RELEASE RIG @ 10:00 PM 09:09-06	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD quiddings.	
Color to 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
SIGNATURE TITLE DRILLING CLERK II DATE OF ON OU	
Type or print name BECKY UTTER E-mail address: becky.utter@apachecorp.com Telephone No. 918-491-5353	
This space for State use).	
OCT 3 0 2006	
APPROVED BY LOUIS OF THE DESCRIPTION DATE	
Conditions of approval, if any:	