

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS***Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE- Other instructions on reverse side.**1. Type of Well
☒ Oil Well ☐ Gas Well ☒ Other2. Name of Operator **SOUTHWEST ROYALTIES, INC.**3a. Address
6 DESTA DRIVE, STE 2100, MIDLAND, TX 797053b. Phone No. (include area code)
432/688-32674. Location of Well (Footage, Sec., T., R., M., or Survey Description)
UNIT K, 1980' FSL & 1980' FWL, SEC 19, T26S, R 37E5. Lease Serial No.
LC030168A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
EAVES A #59. API Well No.
30-025-1201110. Field and Pool, or Exploratory Area
SCARBOROUGH; YATES 7 RIVERS11. County or Parish, State
LEA COUNTY, NM**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-5 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Notify the BLM 24 hrs prior to commencing with P&A procedures.

MI & RU WS. NU BOP.

RIH w/tbg and tag CIBP set @ 2900' and cap w/25 sx cmt.

Pull tbg to 1000' and spot 30 sx cmt (1000' - 900') and tag.

Pull tbg to 300' and spot 30 sx cmt (300' - 200') and tag.

Spot 20sx cmt 60' - 3'.

RD PU; install dry hole marker; cover cellar and pit; clean location.
Prepare to rip & re-seed location and block any roads into well.

Schematic attached.

**APPROVAL SUBJECT TO
GENERAL REQUIREMENTS
AND SPECIAL STIPULATIONS
ATTACHED**14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)**DAWN M. HOWARD**Title **OPERATIONS ASSISTANT**

Signature

Date

10/19/2006**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.


Title

Office


Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW



EAVES "A" #5
 1980' FWL @ 1980' FWL
 Sec. 19, T-26S, R-37E



7 5/8" - 24" CS, @ 1228'
 CMT'D w/ 500 SXS
 <circ'd>

2/14/01 CIBP Set @ 2900'

SQUEEZED 2/87

2937 - 2968'
 2975 - 3035'
 3042 - 3104'
 3112 - 3160'
 3160 - 3177'
 3178 - 3213'

TD @ 3220'

5 1/4" - 14" CS @ 3219'

CMT'D w/ 600 SXS

< TO CC ± 950' per TS >

< Current Condition >

SUNDRY NOTICE SPECIAL STIPULATIONS

- A. Approval is granted to P/A this well with the following modifications to the program:
- B. Increase the cement volume on top of the CIBP to 40 sacks to cover the base of the salt in addition to the completion and tag.
- C. Set a 25 sack cement plug @ 1320' for the top of the salt and surface casing shoe, tag.
- D. Perforate the casing at 100 feet and fill the annulus and the 5 ½ inch casing to the surface with cement.

Engineering
can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 10/25/06