

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-11615
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☒

2. Name of Operator
SMITH & MARRS, INC.

3. Address of Operator
P.O. BOX 863 KERMIT, TX 79745

7. Lease Name or Unit Agreement Name
SOUTH LANGLIE JAL UNIT

8. Well Number #21 WIW

9. OGRID Number
020989

10. Pool name or Wildcat
JALMAT TANSILL YATES 7-RVRS

4. Well Location

Unit Letter I : 2310 feet from the SOUTH line and 330 feet from the

EAST line

Section 18

Township 25S

Range 37E

NMPM

LEA

County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHMENT

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE President DATE 11-16-2006

Type or print name
For State Use Only

E-mail address:

Telephone No.

APPROVED BY: [Signature] TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE NOV 21 2006

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

Smith and Marrs

Lease: South Jal Langley Unit 21 WIW
Project: P & A – CEMENTING REPORT

11/6/2006

TAG CIBP @ 3069' PUMP 25 SACKS CEMENT TAG @ 2915'

11/7/2006

SPOT 55 SACKS @ 2915' - TAG @ 2573'
SPOT 35 SACKS @ 1214' - TAG @ 969'

11/8/2006

PERF AND SPOT 70 SACKS @ 210' - TAG @ 155'

11/9/2006

PERF AND SPOT 70 SACKS @ 155' - CIRCULATING TO SURFACE

PUMP PLUGGING MUD
INSTALLED DRY HOLE MARKER