	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resour	ces May 27, 2004
1625 N. French Dr., Hobbs, NM 88240)	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 882	OIL CONSERVATION DIVISION	ON 30-025-37958
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 8741		6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 C, 14141 07303	6. State Off & Gas Lease No.
87505		
SUNDRY N	OTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	1
DIFFERENT RESERVOIR. USE "AI PROPOSALS.)	PPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Turner State
1. Type of Well: Oil Well	Gas Well 🛛 Other	8. Well Number 4
2. Name of Operator		9. OGRID Number 237788
Plantation Operating, LLC		
3. Address of Operator		10. Pool name or Wildcat
	ite 229, The Woodlands, TX 77380	Eumont (Yates-7 Rivers-Queen) (Gas)
4. Well Location		
Unit Letter B: 660	feet from the <u>North</u> line and	1980 feet from the <u>East</u> line
Section 32		37E NMPM Lea County
Section 32	11. Elevation (Show whether DR, RKB, RT,	
	3525' GR	OK, etc.)
Pit or Below-grade Tank Application	☐ or Closure ☐ Closed-Loop System	
	indwater Distance from nearest fresh water well	Distance from nearest surface water
· ·		
Pit Liner Thickness:		bbls; Construction Material
12. Che	ck Appropriate Box to Indicate Nature of I	Notice, Report or Other Data
	FINTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK AND ALTERING CASING		
I EN ONWINE WEDINE WORK		
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐ COMMEI	VCC ORILLING OPNS. P AND A
	☐ CHANGE PLANS ☐ COMMEI	
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐ COMMEI ☐ MULTIPLE COMPL ☐ CASING	MENT JOB → □ VS
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	☐ CHANGE PLANS ☐ COMME! ☐ MULTIPLE COMPL ☐ CASING/ Recompletion ☐ OTHER!	COMPletion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of the control of the	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent decompleted)	Completion Ails, and River and Riv
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any proposes	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent decompleted)	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of the control of the	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent decompleted)	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any proposes	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent decompleted)	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion.	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent decompleted)	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any proposes	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent decompleted)	Completion Ails, and River and Riv
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006:	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/M	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed GRD, SDL/DSN, CBL logs. Perforate from 3342	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/M	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of of starting any proposed or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" ho	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed GRD, SDL/DSN, CBL logs. Perforate from 3342 sole size). Acidize perfs w/2000 gals 15% HCL acid	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of of starting any proposed or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/M 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Ails, and divergement date including estimated including estimated including estimated date including estimated estimated including estimated estimated including estimated e
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of of starting any proposed or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/M 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor	CHANGE PLANS COMMEI MULTIPLE COMPL CASING Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size is a completed work. MGRD, SDL/DSN, CBL logs. Perforate from 3342 pole size). Acidize perfs w/2000 gals 15% HCL acid work.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/M 19 gram charges 1 SPF (.46" horizontal transfer of the starting any proposed or confidence of the starting any proposed or recompletion.	CHANGE PLANS MULTIPLE COMPL Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed work. GRD, SDL/DSN, CBL logs. Perforate from 3342 belie size). Acidize perfs w/2000 gals 15% HCL acid 0/40 sand and 160,980 pounds of 12/20 sand with 1-3762'. TIH w/110 jts 2-3/8" tbg to 3674'. TIH w	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" horizontal starting any propose or recompletion. Frac well with 39,820 pounds 2 3604". Clean out fill from 3604 production.	CHANGE PLANS MULTIPLE COMPL Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size). Acidize perfs w/2000 gals 15% HCL acid 0/40 sand and 160,980 pounds of 12/20 sand with 1-3762'. TIH w/110 jts 2-3/8" tbg to 3674'. TIH was attion above is true and complete to the best of my kertical properties.	Completion Comple
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" horizontal starting any propose or recompletion. Frac well with 39,820 pounds 2 3604". Clean out fill from 3604 production.	CHANGE PLANS MULTIPLE COMPL Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed size). Acidize perfs w/2000 gals 15% HCL acid 0/40 sand and 160,980 pounds of 12/20 sand with 1-3762'. TIH w/110 jts 2-3/8" tbg to 3674'. TIH was attion above is true and complete to the best of my kertical properties.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" horizontal starting any propose or recompletion. Frac well with 39,820 pounds 2 3604". Clean out fill from 3604 production.	CHANGE PLANS MULTIPLE COMPL Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed work is size. Acidize perfs w/2000 gals 15% HCL acid 0/40 sand and 160,980 pounds of 12/20 sand with 12-3762'. TIH w/110 jts 2-3/8" tbg to 3674'. TIH with the complete with the complete work is true and complete to the best of my keep or closed according to NMOCD guidelines ☒, a general of the complete with t	Completion Comple
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor starting any propose or recompletion. Frac well with 39,820 pounds 2 3604'. Clean out fill from 3604 production.	CHANGE PLANS MULTIPLE COMPL Recompletion OTHER completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed work). SEE RULE 1103. For Multiple Completed work is size. Acidize perfs w/2000 gals 15% HCL acid 0/40 sand and 160,980 pounds of 12/20 sand with 12-3762'. TIH w/110 jts 2-3/8" tbg to 3674'. TIH with the complete with the complete work is true and complete to the best of my keep or closed according to NMOCD guidelines ☒, a general of the complete with t	Completion Ails, and give the ment data including estimated date including estimated estimated including estimated including estimated estimated including estimated including estimated estimated estimated estim
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor Frac well with 39,820 pounds 2 3604'. Clean out fill from 3604 production. I hereby certify that the information grade tank has been/will be constructed.	CHANGE PLANS MULTIPLE COMPL Recompletion CASING/ Recompletion COMMEI CASING/ Recompletion OTHER Completed operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed operations. GRD, SDL/DSN, CBL logs. Perforate from 3342 on the size of the	Completion Ails, and give the ment data including estimated date including estimated estimated including estimated including estimated estimated including estimated including estimated estimated estimated estim
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/N 19 gram charges 1 SPF (.46" hor Frac well with 39,820 pounds 2 3604'. Clean out fill from 3604 production. I hereby certify that the information of the construction of t	CHANGE PLANS MULTIPLE COMPL Recompletion CASING Recompleted operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed size). Acidize perfs w/2000 gals 15% HCL acid of the size). Acidize perfs w/2000 gals 15% HCL acid of the size). Acidize perfs w/2000 gals 15% HCL acid of the size). TIH w/110 jts 2-3/8" tbg to 3674'. TIH w/13/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/M 19 gram charges 1 SPF (.46" hor of the starting and the starting	CHANGE PLANS MULTIPLE COMPL Recompletion CASING Recompleted operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed size). Acidize perfs w/2000 gals 15% HCL acid of the size). Acidize perfs w/2000 gals 15% HCL acid of the size). Acidize perfs w/2000 gals 15% HCL acid of the size). TIH w/110 jts 2-3/8" tbg to 3674'. TIH w/13/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'.	Completion Compl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or of of starting any propose or recompletion. 9/13/2006 through 10/2/2006: TIH w/ 2-3/8" tbg. Run DLL/M 19 gram charges 1 SPF (.46" hor of the starting and the starting	CHANGE PLANS MULTIPLE COMPL Recompletion CASING Recompleted operations. (Clearly state all pertinent ded work). SEE RULE 1103. For Multiple Completed size). Acidize perfs w/2000 gals 15% HCL acid of the size). Acidize perfs w/2000 gals 15% HCL acid of the size). Acidize perfs w/2000 gals 15% HCL acid of the size). TIH w/110 jts 2-3/8" tbg to 3674'. TIH w/13/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TIH w/15/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'. TITLE Produced by the size of the best of my k/10 jts 2-3/8" tbg to 3674'.	Completion Compl

Conditions of Approval (if any)