

OCD-HOBBS

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well  
☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator SMITH & MARRS, INC.

3a. Address  
P.O. BOX 863 KERMIT, TX 79745

3b. Phone No. (include area code)  
432-586-3076

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SESW 22, T-26S, R-37E

1980 FWL, 660 FSL

5. Lease Serial No.

NMLC030174A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

RHODES

8. Well Name and No.

RHODES # 4

9. API Well No.

30-025-12036

10. Field and Pool, or Exploratory Area

RHODES

11. County or Parish, State


LEA COUNTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

SEE ATTACHMENT



14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Terri Jennings

Title Agent

Signature

*Terri Jennings*

Date

10-25-2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

*Wesley W. Ingram*

OC FIELD REPRESENTATIVE II/STAFF MANAGER

Title

DEC 11 2006

Date

NOV 28 2006

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

WESLEY W. INGRAM  
PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW

MAYO MARRS CASING PULLING INC.  
BOX 863  
KERMIT, TEXAS 79745

Smith and Marrs

Lease: Rhodes Fed B # 4  
Project: P & A - CEMENTING REPORT

10/3/2006  
SET CICR @ 2999' PUMP 25 SACKS CEMENT LEAVING SOME ON TOP

10/5/2006  
CUT CASING @ 2016' - NOT LOOSE  
SPOT 25 SACKS FROM 2067' - TAG @ 1790'

10/6/2006  
CUT CASING @ 1265' - PULL CASING

10/10/2006  
SPOT 50 SACKS @ 1333' - NO TAG  
SPOT 50 SACKS @ 1333' - TAG @ 1304'

10/11/2006  
SPOT 50 SACKS @ 1304' - TAG @ 1257'

10/12/2006  
SPOT 50 SACKS @ 1257' - TAG @ 1057'

10/16/2006  
SPOT 35 SACKS @ 515' - TAG @ 379'  
SPOT 15 SACKS @ 60' - CIRCULATE TO SURFACE

PUMP PLUGGING MUD  
INSTALLED DRY HOLE MARKER