

## OCD-HOBBS

Form 3160-5  
(April 2004)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE- Other instructions on reverse side.**

1. Type of Well ☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator **ConocoPhillips Company ATTN: Celeste Dale**

3a. Address  
**4001 Penbrook, Odessa, Texas 79762**

3b. Phone No. (include area code)  
**432-368-1244**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
**Unit Letter B; 380 FSL & 2,310 FWL, Section 25, T-17-S, R-32-E**

5. Lease Serial No.

**LC058697B**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

**~~071058697B~~**

8. Well Name and No.

**Pearl B #4**

9. API Well No.

**30-025-25358**

10. Field and Pool, or Exploratory Area

**Pearsall Queen**

11. County or Parish, State

**Lea, New Mexico**

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent matters and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

10/23/06 Set steel working pit. Moved plugging equipment to location. SDFN.

10/24/06 Notified BLM, Marlin Deaton, on location. Attended safety stand-down in Hobbs. Drove to location, held safety meeting. RU Triple N rig #24 & plugging equipment. WO wellhead, dug out cellar, ND wellhead, NU BOP. RIH w/ 109 jts 2 1/2" workstring tubing to 3,466'. RU cementer and loaded hole w/ mud, pumped 45 sx C cmt w/ 2% CaCl<sub>2</sub> 3,466 - 3,328'. PUH w/ tubing and WOC. RIH w/ tubing, tagged cmt @ 3,333'. Circulated hole w/ mud and POOH w/ tubing to 2,603'. Pumped 40 sx C cmt @ 2,603'. PUH w/ tubing, SDFN.

10/25/06 Notified BLM, Marlin Deaton, on location. Held safety meeting. RIH w/ tubing, tagged cmt @ 2,444'. Finished circulating hole w/ mud, POOH w/ tubing to 1,365'. Pumped 95 sx C cmt w/ 2% CaCl<sub>2</sub> @ 1,365'. PUH w/ tubing and WOC. RIH w/ tubing, tagged cmt @ 1,101' (ok'd per Marlin Deaton). POOH w/ tubing to 444' and pumped 40 sx C cmt w/ 2% CaCl<sub>2</sub> 444 - 321'. POOH w/ tubing. WOC and RIH w/ tubing, tagged cmt @ 317', POOH w/ tubing. ND BOP and RIH w/ tbg to 63'. Circulated 35 sx C cmt 63' to surface. POOH w/ tbg, RDMO.

Cut off wellhead & anchors, installed dryhole marker, backfilled cellar.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

**James F. Newman, P.E.**Title **Engineer, Triple N Services, Inc. 432-687-1994**

Signature

Date

**10/27/2006****THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

**ACCEPTED FOR RECORD****NOV 28 2006****FREDERICK WRIGHT  
PETROLEUM ENGINEER**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**GW**