

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO.	30-025-12190
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. B-9309	
7. Lease Name or Unit Agreement Name Amoco State S	
8. Well Number	2
9. OGRID Number	012024
10. Pool name or Wildcat Tubb Oil & Gas	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
John H. Hendrix Corporation

3. Address of Operator
P. O. Box 3040
Midland, TX 79702-3040

4. Well Location
Unit Letter D : 660 feet from the North line and 660 feet from the West line
Section 32 Township 22S Range 38E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3383' DF

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Steel Depth to Groundwater >100 Distance from nearest fresh water well >1000' Distance from nearest surface water >1000'

Pit Liner Thickness: mil Below-Grade Tank: Volume bbbs; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Perf. Tubb & DHC w/ Blinebry & Drinkard ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Drill out CIBP at 5680'.
2. Cut over CIBP at 6795'. (Well was originally Drinkard.) To re-establish Brunson-Drinkard Abo, S.
3. Perf. additional Brunson-Drinkard Abo, S. 6344 - 6786'.
4. Perf. Tubb - 6133 - 6272'.
5. Set RBP at 6841'.
6. Acidize & frac new perfs. 6133 - 6786'.
7. Swab test Tubb for completion information.
8. DHC Blinebry - Tubb & Brunson Drinkard Abo, S.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Ronnie H. Westbrook TITLE Vice President DATE 12/06/2006

Type or print name Ronnie H. Westbrook

E-mail address:

Telephone No. (432)684-6631

For State Use Only

APPROVED BY: Chris Williams

TITLE OCD DISTRICT SUPERVISOR/GENERAL MANAGER

DATE

Conditions of Approval (if any):

DEC 15 2006