Form 3160-5 (August 1999)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

5. Lease Serial No.

891038170 - NM7488

6. If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WOCD-HOBBS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

7. If U	nit or CA/Ag	reement, N	lame and/or No
Myers	Langlie	Mattix	Unit

SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or N Myers Langlie Mattix Unit			
1. Type of Well Oil Well Gas Well X Other Injection							
Name of Operator     OXY USA WTP Limited Partnership		192463		9. API Well N	io.		
3a. Address       3b. Phone No. (include area code)         P.O. Box 50250, Midland, TX 79710-0250       432-685-5717			30-025-26970 10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., T., R., M., or Survey L 660 FSL 1980 FEL SWSE(0) Sec 4 T2					ttix 7Rvr Qn-GB		
				11. County or Lea	Parish, State		
12. CHECK APPROPRIATE	BOX(ES) TO INC	DICATE NATURE OF I	NOTICE, REPO				
TYPE OF SUBMISSION	TYPE OF ACTION						
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize  Alter Casing  Casing Repair  Change Plans  Convert to Injection	Deepen Fracture Treat New Construction X Plug and Abandon Plug Back	Production Reclamatio Recomplet Temporaril Water Disp	e y Abandon	Water Shut-Off Well Integrity Other		
<ol> <li>Describe Proposed or Completed Operation (clearly</li> </ol>	y state all pertinent detail	ils, including estimated starti	ing date of any pro	posed work and	approximate duration thereof.		

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

8-5/8" 24# csg @ 516' w/350sx, 12-1/4" hole, TOC-Surf-Circ 5-1/2" 14# csg @ 3750' w/1650sx, 7-7/8" hole, TOC-Surf-Circ

PERFS-3460-3694'

1. RIH & Set @ 3410' dump 5sx cmt

PBTD-3720'

2. M&P 25sx cmt @ 2750-2650'

TD-3750'

- 3. M&P 25sx cmt @ 1100-1000'
- 4. M&P 25sx cmt @ 568-468' WOC-Tag
- 5. M&P 15sx cmt Surface Plug 10# MLF between plugs



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart	Γitle S	r. Regula	tory	Analyst			
for find	Date	12 (8)	56	APPR	OVED		
THIS SPACE FOR FEDERAL	OR STAT	TE OFFICE					
Approved by	Title			NEC	Date 2006		
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject least which would entitle the applicant to conduct operations thereon.	Office Ge			DEC	ICK WRIGHT		
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter with the section of th	person know	wingly and wil	lfully to	PERROVE	HM ENGINE	y of the	United

OXY USA WTP LP Myers Langlie Mattix Unit #183 API No. 30-025-26970


15sx Surface

25sx @ 568-468' WOC-Tag

25sx @ 1100-1000'

25sx @ 2750-2650'

CIBP @ 3410' w/ 5sx



12-1/4" hole @ 516' 8-5/8" csg @ 516' w/350sx-TOC-Surf-Circ

7-7/8" hole @ 3750' 5-1/2" csg @ 3750' w/1650sx-TOC-Surf-Circ

Perfs @ 3460-3694'

## SUNDRY NOTICE SPECIAL STIPULATIONS

<ol> <li>Approval is granted to plug this well with the following modifications to the proposed procedure:</li> </ol>
2. All plugs below the surface plug should be tagged for casing shoes and the top and base of the salt.
*All plugs below the surface plug must be at least 100' and 25 sacks of cement.
Ti e de contra a
Engineering can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 12/13/06