

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Injector

2. Name of Operator
Occidental Permian Limited Partnership Attn: Mark Stephens, 19.013, GRWY 5

3a. Address P.O. Box 4294, Houston, TX 77210-4294
3b. Phone No. (include area code) (713) 366-5158

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2378' FNL x 1086' FWL, Letter E, Sec. 29, T-18-S, R-38-E

5. Lease Serial No.

LC-032233(A)

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

North Hobbs G/SA No. 712
Unit

9. API Well No.

30-025-37558

10. Field and Pool, or Exploratory Area
Hobbs; Grayburg-San Andres

11. County or Parish, State

Lea Co. NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other Squeeze &

Reperforate

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

- 1) MI x RU. NU BOP x POOH with injection equipment.
- 2) Run bit x scraper to PBTD (4326'). Set CIBP in 5-1/2" casing at 4165'
- 3) TIH with CICR at set at 4080'. Establish injection into perfs at 4124' - 4151'.
- 4) Cement squeeze 4124' - 4151' per Halliburton recommendation.
- 5) Drill out CICR and test to 1000 psi.
- 6) Drill out cement and CIBP to bottom.
- 7) Re-perf at 4150' w/2 JSPF.
- 8) RIH with 5-1/2" PPI tool and acid treat 4173' - 4300' with 1470 gal. 15% HCL
- 9) Swab or flow back spent acid x circulate well clean.
- 10) RBIH with injection equipment x pressure test casing.
- 11) ND BOP and RD x MO. Put well back on injection and clean location.

SUBJECT TO LIKE APPROVAL BY STATE

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Mark Stephens

Title

Regulatory Compliance Analyst

Date

12/11/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OC DISTRICT SUPERVISOR/GENERAL MANAGER

Date

DEC 18 2006

DEC 22 2006

WESLEY W. INGRAM
PETROLEUM ENGINEER

