Form 3160-5 (April 2004) r	UNITED STATE DEPARTMENT OF THE		OCD-HOBI	OMBN	APPROVED 10. 1004-0137				
SUNDRY	LLS	Expires: March 31, 2007 5. Lease Serial No. LC 059001							
Do not use th	nis form for proposals f ell. Use Form 3160-3 (o drill or to re-	enter an	6. If Indian, Allottee	or Tribe Name				
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No. 8920003410 NM 76937								
1. Type of Well Oil Well		8. Well Name and N MCA Unit #22	lo.	<u> </u>					
2. Name of Operator ConocoPhilli		9. API Well No. 30-025-00798							
3a Address 3300 N. "A" Street, Bldg. 6 #2		3b. Phone No. (include 432-688-6884	e area coae)	10. Field and Pool, or Exploratory Area Maljamar Grayburg/San Andres					
 Location of Well (Footage, Sec., Unit Letter "D", 660' FNL & 		11. County or Parish, State Lea, New Mexico							
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATU	RE OF NOTICE, R	EPORT, OR OTHE	R DATA				
TYPE OF SUBMISSION		PE OF ACTION							
Notice of Intent	Acidize	Deepen Fracture Treat	Production (Sta		ater Shut-Off ell Integrity her				
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon Plug Back	Recomplete						
determined that the site is ready	nal Abandonment Notices shall be / for final inspection.) OSED PLUGGING PROCED		-	ation, have been comple	ited, and the operator	has			
14. I hereby certify that the fore Name (Printed/Typed)									
Circusture			Title Engineer, Triple N Services, Inc.						
Signature	THIS SPACE FOR			2/16/2006	WED				
Approved by Langue Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to Title 18 U.S.C. Section 1001 and Title States any false, fictitious or fraudul (Instructions on page 2)	attached. Approval of this notice or equitable title to those rights i o conduct operations thereon.	n the subject lease	SENTATIVE II/S	TAFF MANAGE Date DEC 2		6 200			
GWW			Ŀ						



T:\Jim Data\Client Files\CONOCO\Wellbore Diagrams\MCA wellbores\MCA Unit #220 WBDs.xls



ConocoPhillips

Proposed Plugging Procedure

MCA Unit #220W API #30-025-00798 Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

Casings: 8¼" 32# casing @ 1,195' cmt'd w/ 50 sx, TOC unknown 7" 20# casing @ 3,567' cmt'd w/ 100 sx, TOC unknown 4½" 9.5# liner @ 3,815' cmt'd w/ 300 sx, TOC @ 125' Openhole 3,820 – 3,915'

- TA'd w/ Loc-set packer & K-valve set @ 3,515' (set 07/14/92)
- Bradenhead squeezed w/ 20 bbls flow-check & 100 sx H cmt due to water flow
- Notify BLM & NMOCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- **1.** Set steel pit and flow down well as needed. MIRU plugging equipment. ND wellhead and NU 6" 5,000# hydraulic BOP.
- RIH w/ 2³/₈" workstring, tag RBP. RU cementer & circulate hole w/ plugging mud. Pump 35 sx C cmt (1.32 ft³/sk yield, 46.2 ft³ slurry volume, calculated fill 507' in 4¹/₂" 9.5# casing) 3,515 3,008'. POOH w/ tubing. *Grayburg San Andres & previous squeeze plug*
- **3.** RU lubricator and RIH w/ four 3½" strip-jet perforating charges on wireline, and perforate 4½" & 7" casings with four squeeze holes @ 2,130'. POOH w/ wireline.
- 4. RIH w/ AD-1 packer to 1,500'. Load hole w/ mud and set packer. Establish rate into perforations at 1,500 psi or less. Squeeze 40 sx C cement w/ 2% CaCl₂ (1.32 ft³/sk yield, 52.8 ft³ slurry volume, calculated fill 156' in 7%" open hole) 2,130 1,974'. WOC & tag this plug no deeper than 2,030'. POOH w/ packer. If unable to establish rate at 1,500 psi or less, contact both BLM & NMOCD for balanced plug approval. Base of salt plug
- 5. RIH w/ four 3½" strip-jet perforating charges on wireline, and perforate 4½" & 7" casings with four squeeze holes @ 1,245'. POOH w/ wireline.
- 6. RIH w/ AD-1 packer to 600'. Load hole w/ mud and set packer. Establish rate into perforations at 1,500 psi or less. Squeeze 75 sx C cement w/ 2% CaCl₂ (1.32 ft³/sk yield, 99.0 ft³ slurry volume, calculated fill 293' in 7%" open hole) 1,245 952'. WOC & tag this plug no deeper than 995'. POOH w/ packer. If unable to establish rate at 1,500 psi or less, contact both BLM & NMOCD for balanced plug approval. Surface casing & top of salt plug
- **7.** RIH w/ four 3½" strip-jet perforating charges on wireline, and perforate 4½" & 7" casings @ 400'. POOH w/ wireline.

- RIH w/ AD-1 packer to 180'. Load hole w/ mud and set packer. Establish rate into perforations at 800 psi or less. Squeeze 80 sx C cement w/ 2% CaCl₂ (1.32 ft³/sk yield, 106 ft³ slurry volume, calculated fill 129' in 12¼" open hole) 400 271'. WOC & tag this plug no deeper than 300'. POOH w/ packer. If unable to establish rate at 800 psi or less, contact both BLM & NMOCD for balanced plug approval. *Freshwater plug*
- **9.** RIH w/ four 3½" strip-jet perforating charges on wireline, and perforate 4½" & 7" casings @ 100'. POOH w/ wireline.
- 10. ND BOP, NU wellhead. Establish rate into perforations at 500 psi or less and circulate 80 sx C cement (1.32 ft³/sk yield, 106 ft³ slurry volume, calculated fill 129' in 12¼" open hole) 100' to surface. If unable to establish rate at 500 psi or less, contact both BLM & NMOCD for balanced plug approval. *surface plug*
- **11.** RDMO location. Clean steel pit & haul fluids to disposal. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

PROPOSED PLUGGED WELLBORE SKETCH

.*

· . . .

ConocoPhillips Company -- Mid-Continent BU / Odessa

Date: December 16, 2006

RKB @ 3928'						Da	ate:	Decen	ber 16, 3	2006	-
DF @ 3927'		.		Liebee							
GL @ <u>3917'</u>	iL @ <u>3917'</u>		Subarea : Lease & Well No. :		Hobbs MCA Unit No. 220W						-
		Legal Description			& 660' FEL, Se		17-S, R-	32-E			
	Perf & sqz 80 sx C cmt 100'	County :		Lea	State :	_	ew Mexic	0			
	to surface, circ cmt	Field :		Maljamar							•
	TOC 4-1/2" Liner @ 125'	Date Spudded :		May 23, 1939		Release	ed: Ai	ıg. 9, 1939)		-
	Bradenhead Sqz surf-Int csg annulus w/20 bbls flow-check	API Number : Status:	PROPOSE	30-025-00 D PLUGGED)/98						-
	w/100 sx Class H cement	Clatus.			Lease	Serial I	No.	LC	C-05900	1	•
<u>XA IIII XXA</u>	Perf & sqz 80 sx C cmt 400 - 300'	Stimulation His	tory:								
	TAG		D -4-	T	C -1		bs.	Max		Max	Down
		Interval	<u>Date</u>	<u> Type</u>	Ga	<u>18 38</u>	and	Press	IGIP	Rate	<u>Down</u>
	Hole Size N / A	36641-3801	12/16/40		2 0	ts Nitro					
		3820-3915	8/11/47			Qts Nit					
			6/25/54	Plug back to 350 Perf 3198-3238		BP @ 3	500' w/1	1/2 sx on	top.		
		3198-3238	6/28/54	Oil		000 20	0.000	2800		11.0	
			8/18/56	Squeeze 3198-3	3238 w/100 sx	cement	-				
	Top Salt @ 1095'		8/20/56	Drill out cmt & C		np 1 sx (Calseal in	h btm of ho	ole.		
	8-1/4" 32# @ 1,195' w/ 50 sx	3567 3894	8/04/50	Top of Calseal @ Gelied Crude	-	000 15	5 000	3400		18.5	
	Perf & sgz 75 sx C cmt 1,245 - 995'	3567-3884	8/21/56 2/20/687	Gelled Crude Cleanout from 3		000 15	,000	3400		10.0	
	r en a eus re ex o unit 1,245 - 555		3/2/68	Convert to water							
			8/24/72	Set 4-1/2" 9.5#							
			6/18/84	Sqz csg leaks (
			8/85	Bradenhead Sq w/20 bbis flow-					ulus		
			1/1/88	Shut-in		~ 01400		~			
			10/7/88	placed back on i	njection						
			7/14/92	1.71 R Profile N			F 4 F1				
				Baker Loc Set I Temporarily Ab		Set @ 3	515				
				remporting rus				_			
	Base Sait @ 2030'				<u> </u>						
		-		SERVI	PLE N						
	Perf & sqz 40 sx C cmt 2,130 - 2,030'	IAG		MIDLAND, T							
				PROPOSED	PLUGGING	3 PRO	CEDU	RE			
					BP @ 3,515', i				3'		
					sqz 40 sx C c						
					sqz 75 sx C c sqz 80 sx C c						
				,	sqz 80 sx C c				nt		
				-,							
										1	
				Casing / Openh	ole Capacities						
				41⁄2" 9.5# csg:	10.96	5 ft/ft3		0.0912	ft3/ft		
				51/2" 17# csg:		1 ft/ft3 9 ft/ft3		0.1305 0.2273	ft3/ft ft3/ft		
xx ///// xx	3198-3238 Sqz'd w/100 sx			7" 20# csg: 7" 26# csg:		5 ft/ft3		0.2273	ft3/ft		
				7%" 24# csg:	3.715	5 ft/ft3		0.2691	ft3/ft		
	Tag RBP @ 3,515', 35 sx C cmt 3,515	- 3,008'		8%" 20# csg:		3 ft/ft3		0.3659	ft3/ft		
	BP @ 3500' w/1-1/2 sx drilled out Baker Lockset w/K Valve RBP @ 3515'			8%" 24# csg: 8%" 28# csg:		7 ft/ft3 3 ft/ft3		0.3575 0.3505	ft3/ft ft3/ft		
	Guiberson Pkr w/plug set @ 3541'				2.000			0.0000			
	Hole Size N / A			6¾" openhole:		ft/ft3			ft3/ft		
- KAOL - KAOL	7" 20#@(3566.5' 3647 } Cmt'd w/100 sx 3686 } - Csg le	aks sqz'd w/70 s	v	7¼" openhole: 9½" openhole:	2.957	7 ft/ft3 2 ft/ft3			ft3/ft ft3/ft		
- 1775 ISSN	TOC @ N / A	una aqr u W//U S 		10" openhole:		ft/ft3			ft3/ft		
	Hole Size N / A			121/4" openhole:		ft/ft3			ft3/ft		
	4-1/2" 9.5# J-55 LINER @ 3815' cmt'd w/	300 sx, TOC 125			aven Divers						
					Seven Rivers Grayburg 4th		3680'				
	<u>OH 3567-3992'</u>				Grayburg 5th		3741'				
	3820-3915 - Shot w/450 Quarts			G	Grayburg 6th		3818'				
	CALSEAL TOP @ 3884'										
	JUNK IN HOLE @ 3952'										
PBTD @ 3541'	1										
TD @ 4283'	ł.										

1

ļ

SUNDRY NOTICE SPECIAL STIPULATIONS

- 1. Approval is granted to plug this well with the following modifications to the proposed procedure:
- 2. Retrieve the RBP @ 3515', packer @ 3541 and set 25 sack minimum cement plug @ 3815' for 7" casing shoe and open hole, <u>if RBP and packer can be</u> <u>retrieved</u>.
- 3. If RBP and packer cannot be retrieved, proceed with procedure as submitted.
- 4. Plugs @ bottom, 2130' and 1245' should be tagged.

***All plugs below the surface plug must be at least 100' and 25 sacks of cement.

ALL OF THE WORK AUTHORIZED HERE MUST BE COMPLETED WITHIN 90 DAYS.

<u>Engineering</u> can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 12/21/06