Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resource	es May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	,	WELL API NO.
District II	OIL CONSERVATION DIVISION	N 30-025-05217
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTI (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC	CES AND REPORTS ON WELLS 2015 SEP SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	28 Ph Lease Name or Unit Agreement Name
PROPOSALS.)	Gas Well Other	8. Well Number 9
Type of Well: Oil Well Name of Operator	Gas Well Guici	9. OGRID Number 236378
Saber Resources LLC		
3. Address of Operator		10. Pool name or Wildcat
400 W. Illinois, Ste 950, Midland,	Texas 79701	Denton Devonian
4. Well Location		•
Unit Letter C:	660 feet from the North line	and1650feet from the _Westline
Section 36	Township 14S Range	37E NMPM Lea County
Section 30	11. Elevation (Show whether DR, RKB, RT, C	
Pit or Below-grade Tank Application 0	3804' GR r Closure □	
	Distance from nearest fresh water well	Distance from nearest surface water
··· —— ·		Material Earth & synthetic liner
12. Check A	Appropriate Box to Indicate Nature of N	otice, Report or Other Data
NOTICE OF IN	TENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	· · · · · · · · · · · · · · · · · · ·	L WORK
	· · · · · · · · · · · · · · · · ·	-
	CHANGE PLANS II I COMMENI	CEDRILLING OPNSTI PANDA LI
TEMPORARILY ABANDON DULL OR ALTER CASING		CE DRILLING OPNS. P AND A
TEMPORARILY ABANDON DULL OR ALTER CASING		CE DRILLING OPNS. P AND A C
PULL OR ALTER CASING OTHER:	MULTIPLE COMPL ☐ CASING/C	return well to production
OTHER: 13. Describe proposed or comp	MULTIPLE COMPL CASING/C OTHER: letted operations. (Clearly state all pertinent details)	return well to production ails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp	MULTIPLE COMPL CASING/C OTHER: letted operations. (Clearly state all pertinent details)	EMENT JOB
OTHER: 13. Describe proposed or comp	MULTIPLE COMPL CASING/C OTHER: letted operations. (Clearly state all pertinent details)	return well to production ails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion.	MULTIPLE COMPL CASING/CO OTHER: letted operations. (Clearly state all pertinent detectors). SEE RULE 1103. For Multiple Completic	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 – 9/06/06 MIRU P	MULTIPLE COMPL CASING/CONTROL OTHER: Ideted operations. (Clearly state all pertinent deteork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion disproduction tubing. Clean out wellbore to top
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 7/28/06 – 9/06/06 MIRU Plof retainer at 12,489'. Drille	MULTIPLE COMPL OTHER: letted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion J. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion diproduction tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485' –
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 7/28/06 – 9/06/06 MIRU Pl of retainer at 12,489'. Drille 12,620' with 190 holes. RIF	MULTIPLE COMPL OTHER: Other:	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIFsub pump on new tbg to 11,3	MULTIPLE COMPL OTHER: letted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion J. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 7/28/06 – 9/06/06 MIRU Pl of retainer at 12,489'. Drille 12,620' with 190 holes. RIF	MULTIPLE COMPL OTHER: Oleted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 My/pkr & acidize Devonian perfs with 11,000 gr	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD ell tested 188 BO, 200 MCF & 2001 bbl
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIFsub pump on new tbg to 11,3	MULTIPLE COMPL OTHER: Oleted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 My/pkr & acidize Devonian perfs with 11,000 gr	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIFsub pump on new tbg to 11,3	MULTIPLE COMPL OTHER: Oleted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 My/pkr & acidize Devonian perfs with 11,000 gr	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD ell tested 188 BO, 200 MCF & 2001 bbl
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIFsub pump on new tbg to 11,3	MULTIPLE COMPL OTHER: Oleted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 My/pkr & acidize Devonian perfs with 11,000 gr	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD ell tested 188 BO, 200 MCF & 2001 bbl
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIFsub pump on new tbg to 11,3	MULTIPLE COMPL OTHER: Oleted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 My/pkr & acidize Devonian perfs with 11,000 gr	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD ell tested 188 BO, 200 MCF & 2001 bbl
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIFsub pump on new tbg to 11,3	MULTIPLE COMPL OTHER: Oleted operations. (Clearly state all pertinent detaork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 My/pkr & acidize Devonian perfs with 11,000 gr	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD ell tested 188 BO, 200 MCF & 2001 bbl
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Pl of retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,3 water on 9/19/06.	MULTIPLE COMPL OTHER: OTHER:	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Pl of retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,3 water on 9/19/06.	MULTIPLE COMPL OTHER: Ileted operations. (Clearly state all pertinent detectors). SEE RULE 1103. For Multiple Completion J. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 I w/pkr & acidize Devonian perfs with 11,000 grazes. Returned well to production on 9/6/06. We above is true and complete to the best of my km.	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Pl of retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,3 water on 9/19/06.	MULTIPLE COMPL	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan .
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Pl of retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,3 water on 9/19/06.	MULTIPLE COMPL OTHER: Ileted operations. (Clearly state all pertinent detectors). SEE RULE 1103. For Multiple Completion J. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 I w/pkr & acidize Devonian perfs with 11,000 grazes. Returned well to production on 9/6/06. We above is true and complete to the best of my km.	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan .
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,2 water on 9/19/06. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	MULTIPLE COMPL OTHER: OTHER: OTHER:	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion of production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD ell tested 188 BO, 200 MCF & 2001 bbl Owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . ident of Operations DATE
OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,3 water on 9/19/06. I hereby certify that the information grade tank has been/will be constructed or	MULTIPLE COMPL OTHER: OTHER: OTHER:	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion of production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD ell tested 188 BO, 200 MCF & 2001 bbl Owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . ident of Operations DATE
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,2 water on 9/19/06. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Douglas Keathley	MULTIPLE COMPL OTHER: OTHER: OTHER:	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion of production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . ident of Operations DATE .com Telephone No. 432-685-0169
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,2 water on 9/19/06. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	MULTIPLE COMPL OTHER: Ideted operations. (Clearly state all pertinent detrork). SEE RULE 1103. For Multiple Completion U. POH with rods & pump. POH, Lay down old dout retainer & cmt. Cleanout well to TD of 12 I w/pkr & acidize Devonian perfs with 11,000 grants. Returned well to production on 9/6/06. We closed according to NMOCD guidelines , a general performance of the	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion of production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . ident of Operations DATE .com Telephone No. 432-685-0169
OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,2 water on 9/19/06. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Douglas Keathley	MULTIPLE COMPL OTHER: OTHER:	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion of production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . ident of Operations DATE .com Telephone No. 432-685-0169
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/28/06 - 9/06/06 MIRU Plof retainer at 12,489'. Drille 12,620' with 190 holes. RIF sub pump on new tbg to 11,2 water on 9/19/06. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Douglas Keathley	MULTIPLE COMPL OTHER: OTHER:	return well to production ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion of production tubing. Clean out wellbore to top 2,635'. Perf Devonian from 12,485'— als 15% NEFE acid. Ran 2400 BPD cell tested 188 BO, 200 MCF & 2001 bbl owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . ident of Operations DATE .com Telephone No. 432-685-0169