Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

LES BABYAK

PETROLEUM ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

5. Lease Serial No. NM0202771A

				_		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. NM 061P3587C427	
1. Type of Well ☐ Gas Well ☐ Other			8. Well Name and No.			
2. Name of Operator Novy Oil & Gas, Inc.					Government C Com #1 9. API Well No. 30-025-23737	
3a. Address 125 N. Market, Suite 1230, Wichita, KS 67202		3b. Phone No. (include area code) 316-265-4651		10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Vada Penn 11. County or Parish, State			
Unit Letter "G" 1980' FNL & 1830' FEL, SW NE Sec. 1-9S-34E						
,			Lea Co., NM			
12. CHECK APPROPRIATE	BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OR (OTHER DATA	
TYPE OF SUBMISSION		TYF	PE OF ACTION			
	nsing [Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (State Reclamation Recomplete Temporarily Al Water Disposal	[[bandon	Water Shut-Off Well Integrity Other	
13. Describe Proposed or Completed Operation (cle If the proposal is to deepen directionally or reco Attach the Bond under which the work will be p following completion of the involved operation testing has been completed. Final Abandonmer determined that the site is ready for final inspect (1) Move in and rig up unit. (2) Release packer and pull 3 joints tub (3) Rig up Halliburton & cement squee	emplete horizontally performed or provides. If the operation of the Notices must be tion.) Sing. Reset packet tize Abo perfs fro	y, give subsurface location de the Bond No. on file v results in a multiple comp filed only after all require er @ 8745'.	ns and measured and trovith BLM/BIA. Requirelection or recompletion ments, including reclan	ue vertical depths red subsequent rep in a new interval, nation, have been	of all pertinent markers and zones. corts must be filed within 30 days a Form 3160-4 must be filed once completed, and the operator has PROVED	

(4) Pull out of hole with tubing and packer.

(5) Pick up 6 - 4 1/4" drill collars with 4 3/4" bit, six collars and trip in hole on tubing.

(6) Drill out cement. Test squeeze to 1500#.

(7) Continue in hole and drill bridge plug @ 9040'. Pull out of hole with bit & collars.

(8) Pick up overshot, jars, bumper sub, drill collars and trip in hole.

(9) Latch on to fish - 1 joint 2 3.8" tubing and tubing anchor. Knock loose and pull out of hole.

(10) Clean out to PBTD @ 9758'.

(11) Run production equipment, tubing and rods. Put on pump. Pump Bough "C" perfs - 9278-34'.

ANTICIPATE WORK TO START JULY 10, 2006 OR AS SOON AS A RIG IS AVAILABLE

			<u> </u>				
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)			4 /3				
Frank E. Novy	Title President						
Signature Evante E. Havy	Date	06/20/2006					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	Title	Date					
Conditions of approval, if any, are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	rant or lease Office						
		310.11	Cala IIa ta d				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

