· · · · · · · · · · · · · · · · · · ·			
Submit 3 Copies To Appropriate District Office State of New Mexico			Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 87240		WELL API N	Revised March 25, 1999 O.
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION			30-025-22151
District III 2040 South Pacheco 1000 Rio Brazos Rd., Aztec, NM 87410		5. Indicate Type of Lease STATE X FEE	
District IV 2040 South Pacheco, Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
		7 Lease Nam	ne or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		State "GG"	ic of Ollit Agreement Name
1. Type of Well: Oil Well Gas Well OtherRe-entry Dry Hole			
2. Name of Operator Concho Oil & Gas Inc.		8. Well No.	1
3. Address of Operator 550 W. Texas Ave., Suite 1300		9. Pool name or Wildcat	
Midland, Texas 79701 4. Well Location		Undes; Devo	nian
Unit Letter J : 1980 feet from the South	line and 1980	<u>feet</u>	from the East line
	ange 34E	NMPM	County Lea
10. Elevation (Show whether DR, 4139	RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOBS		
OTHER:	OTHER:		
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion. 7-2-03 MIRU Typer WSU.Began operations to re-enter. 7-8-03 Tag surf plug @ 85' DO to 95'. Circ. clean 710-03 Tag cmt plug @ 2020'. Test pipe rams to 1000 psi. Drld to 2027'. Circ clean. 7-11-03 Drld cmt from 2027' to 2037'. Bit started mg rough on junk from 2037' to 2042' & quit. All inside teeth worn flat. 7-12-15-03 Cont cut over junk. Made 3" in 2 hrs. LD swivel. TIH & tag @ 2042'. Mill 1 3/4" to 2044' in 3 3/4 hrs. Rec metal fines banding. Circ. clean. 7-16-03 PU 65 jts 2 7/8" tbg to 2043'. RUBJ Service. Spot 35 sx Cl. C cmt plug from 1943' to 2043'. LD 52 jts. tbg. Spot 35 sx Cl C + 2% CaCl2 cmt plug from 303' to 403'. LD 13 jts. tbg. WOC 2 hrs. PU 10 jts tbg. Tag plug @ 310'. LD tbg. ND hydril & BOP. Remove B section & spot 10 sx surf plug. WELL P&A'D. 			
Approved as to Plugging of the Well Bore. Liability under bond is retained until			190 25 SE 20 20 20 20 20 20 20 20 20 20 20 20 20
Surface restoration is completed.			
			S JUL 2000
I hereby certify that the information above is true and complete to the best of my knowledge		ge and belief.	h Hobbs
SIGNATURE DATE 07/18/2003			
Type or print name Brenda Coffman			elephone No.
(This space for State use) GE FIELD REPRESENTATIVE IT/STAFF MANAGER			
APPROVED BY Hay W. Wint TITLE Conditions of approval, if any:			D&EP 03 2003
CONGRUONS OF ADDITIVAL. IT ANY:			