

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06980
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	CENTRAL DRINKARD UNIT
8. Well No.	142
9. Pool Name or Wildcat	DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3475' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
CHEVRON USA INC

3. Address of Operator
15 SMITH RD, MIDLAND, TX 79705

4. Well Location
Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST Line
Section 33 Township 21-S Range 37-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3475' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:


PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: C/O, ACIDIZE, LOWER PUMP ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-20-06: MIRU. JAR ON STUCK PUMP.
11-21-06: MI & RACK 222 NEW JTS 2 3/8" TBG. TIH W/BIT TO 4650'.
11-22-06: PUMP 20 BBLS DN TBG & CSG. TIH W/BIT & TAG FILL @ 6513'. PERFS 6514-6601'.
11-27-06: CIRC WELL @ 5300'. TIH TO 6513'. DRILL TO 6514'.
11-28-06: TIH W/MILL SHOE, WP, BMPR SUB, & TAG @ 6514'. CIRC. DRILL 6514-6526, 6536, 6546, 6551. POOH TO ABOVE PERFS.
11-29-06: TIH W/NEW SHOE, 2 JTS WP, DC'S, WS. CIRC W/AIR UNIT @6500. WASH DN 6514-6551. DRILL 6551-6555, 6578. POOH ABOVE PERFS.
11-30-06: TIH W/MILL SHOE & TAG @ 6578. DRILL 6578-6580.
12-01-06: TIH & TAG @ 6578. MILL 6578-6789.
12-04-06: TIH W/SHOE & TAG @ 6590. C/O TO 6611.
12-05-06: TIH W/PKR & SET @ 6461'. ACIDIZE W/7000 GALS ACID.
12-06-06: TBG ON VAC. RU SWAB. MIX 1 DRUM SCALE INHIB W/50 BW. FLUSH W/200 BW.
12-07-06: TOH W/2 7/8" TBG, PERF SUB, X-OVER, TAC.
12-08-06: SET TAC.
12-11-06: TIH W/RHBC, & RODS. SPACE OUT PUMP. LAOD & TEST. RIG DOWN. FINAL REPORT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist

DATE 1/3/2007

TYPE OR PRINT NAME Denise Pinkerton OC FIELD REPRESENTATIVE II/STAFF MANAGER

Telephone No. 432-687-7375

(This space for State Use)

APPROVED Gary W. White OC FIELD REPRESENTATIVE II/STAFF MANAGER
CONDITIONS OF APPROVAL, IF ANY: TITLE

DATE

JAN 10 2007