Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103 May 27, 2004
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resource	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-35556 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE 🛛 FEE 🗌
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	CES AND DEDORTS ON WELLS	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 131
2. Name of Operator		9. OGRID Number
Petrohawk Operating 3. Address of Operator		10. Pool name or Wildcat
1000 Louisisana, Suite 5600 Houston, TX 77002		Jalmat, Tansill, Yates, 7 Rvrs, (Pro Gas)
4. Well Location		
Unit Letter I1650feet from the S line and990feet from the Eline		
Section 9 Township 23S Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3431' RKB		
Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data Policy NOTICE OF INTENTION TO: SUBSEQUENT REPORMODE:		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS P AND PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
FULL ON ALTEN CASING	MOETIFEE COMPE	WENT 30B
OTHER: OTHER: T/A well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
1. Set CIBP @ 3040'. (Current perfs: 3088'-3035')		
2. Load casing w/ 2% KCL water.		
3. Test casing 550# for 30 minutes.		
 4. Record test on chart. (Buddy Hill witness) 5. Request 5 year T/A status. This Approval of Temporary Abandonment Expires		
5. Request 5 year T/A status.	Abandonment Ex	pires/2/26///
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines \square , a general permit \square or an (attached) alternative OCD-approved plan \square .		
SIGNATURE	TITLE_Production Fore	emanDATE 1-8-07
Type or print name Joel Sisk E-mail address: jsisk@petrohawk.com Telephone No.505-394-2574 For State Use Only		
APPROVED BY: Lay W. Wine TITLE REPRESENTATIVE HISTAFF MANAGED ATE Conditions of Approval (if any):		

