Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u>	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	ON CONCERNATION DIVICION	WELL API NO. 30-025-37902
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE V FEE 6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Salita 1 C, INVI 67303	6. State Off & Gas Lease No.
87505	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Λ
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FOR SUCH	Angell
1. Type of Well: Oil Well	Gas Well 🔲 Other	8. Well Number
2. Name of Operator & C. Operator	rating Inc	9. OGRID Number 160825
3 Address of Operator		10. Pool name or Wildcat
POBOX S	50820 Midland, TX 79710	Lovington (Paddock)
4. Well Location Unit Letter A: 660' feet from the North line and 660' feet from the East line		
Unit Letter : 660 feet from the NOTTI line and 660 feet from the CUSI line  Section   Township   TS Range 36E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
38.31′ 6 L Pit or Below-grade Tank Application □ or Closure □		
Pit type Depth to Groundwa		Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   V. ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND		
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	ENT JOB
		2.02
OTHER.	OTHER:	
OTHER:  13. Describe proposed or compl	eted operations. (Clearly state all pertinent details,	and give pertinent dates, including stimated date
13. Describe proposed or comple of starting any proposed wo	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including stimated date Attach wellbore diagram of proposed completion
13. Describe proposed or compl of starting any proposed wo or recompletion.	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed completion
13. Describe proposed or compl of starting any proposed wo or recompletion.	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed completion
13. Describe proposed or compl of starting any proposed wo or recompletion.	eted operations. (Clearly state all pertinent details,	Attach wellbore diagram of proposed completion
13. Describe proposed or complete of starting any proposed we or recompletion.	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH	Attach wellbore diagram of proposed completion  W/thy
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/ 12/27/06 Acidia	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  ye purfy 6234'-6288' W/	W/thy 8000 galv 1570 NEFE +
13. Describe proposed or complete of starting any proposed we or recompletion.  12/26/06 POOH W/ 12/27/06 Acidir 40 ba	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Tooks and pump, POOH  ye perfy 6234'-6288' W/  U sealer AIR 5.9 BPM @	W/thy 8000 gals 15% NEFE + 3500 psi, may rate
13. Describe proposed or complete of starting any proposed we or recompletion.  12/26/06 POOH W/ 12/27/06 Acidir 40 ba	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Tooks and pump, POOH  ye perfy 6234'-6288' W/  U sealer AIR 5.9 BPM @	W/thy 8000 gals 15% NEFE + 3500 psi, may rate
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/ 12/27/06 Acidin 40 ba 6.5 bp	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Troods and pump, POOH  ye perfy 6234'-6288' W/ U sealers AIR 5.9 BPM @  m @ 4400 psi Hushed W/30	Attach wellbore diagram of proposed completion  W/thy  8000 galy 15% NEFE +  3500 pxi, may rate  Obbly 2% KC1
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/ 12/27/06 Acidin 40 ba 6.5 bps	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Prods and pump, POOH  ye perfy 6234'-6288' W/  U sealer AIR 5.9 BPM @  m @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu	W/thy 8000 gals 15% NEFE + 3500 psi, may rate
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/ 12/27/06 Acidin 40 ba 6.5 bp/ 151P-2	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Prods and pump, POOH  y perfy 6234'-6288' W/  U sealer AIR 5.9 BPM @  m @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  ead	Attach wellbore diagram of proposed completion  W/thy  8000 galv 1570 NEFE +  3500 pri, may rate  Obbly 270 Kc1  in 1287 pri; 15 min 641 pri
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/ 12/27/06 Acidin 40 ba 6.5 bp/ 151P-2 well d Ran xx	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  ye perfy 6234'-6288' W/  Ul sealers AIR 5.9 BPM &  m @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  ead  mul rods, pump and they	Attach wellbore diagram of proposed completion  W/thy  8000 gals 15 % NEFE +  3500 pri, may rate  bbbs 2% Kc1  in 1287 pri; 15 min 641 pri  Return to production.
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/  12/27/06 Acidin 40 ba 6.5 bps 151P-2 Well d Ran Do	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  ye perfy 6234'-6288' Wl  U sealers AIR 5.9 BPM @  m @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  ad  whe rods, pump and tly  above is true and complete to the best of my knowle	Attach wellbore diagram of proposed completion  W/thy  8000 gals 15 % NEFE +  3500 pri, may rate  bbbs 2% Kcl  in 1287 pri; 15 min 641 pri  Return to production.  Edge and belief. I further certify that any pit or below-
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/  12/27/06 Acidin  40 ba  6.5 bp  151P-2  Well d  Ran So  I hereby certify that the information grade tank has been/will be constructed or	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  Reperfy 6234'-6288' Wl  U sealers AIR 5.9 BPM @  M @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  ead  Mul rods, pump and tly  above is true and complete to the best of my knowle  closed according to NMOCD guidelines  a general permit	Attach wellbore diagram of proposed completion  W/thy  8000 galy 1570 NEFE +  3500 pri, may rate  O bbly 270 Kcl  in 1287 pri; 15 min 641 pri  Return to Production.  Edge and belief. I further certify that any pit or below-  or an (attached) alternative OCD-approved plan .
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/  12/27/06 Acidin  40 ba  6.5 bp  151P-2  Well d  Ran xo  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  perfy 6234'-6288' Wl  U sealer AIR 5.9 BPM @  M @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  and  whe rods, pump and tlg  above is true and complete to the best of my knowled closed according to NMOCD guidelines \( \), a general permit	Attach wellbore diagram of proposed completion  W/thy  8000 galv 15 70 NEFE +  3500 pri, may rate  0 bbly 270 KCl  in 1287 pri; 15 min 641 pri  Return to production.  Edge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan    DATE 1-4-07
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W/  12/27/06 Acidin  40 ba  6.5 bp  151P-2  Well d  Ran xo  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name KEVIN W	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  perfy 6234-6288' Wl  U sealers AIR 5.9 BPM &  m @ 4400 pri Hushed W/30  593; 5 min 1949 pri; 10 mu  ead  mul rods, pump and tly  above is true and complete to the best of my knowled  closed according to NMOCD guidelines  a general permit	Attach wellbore diagram of proposed completion  W/thy  8000 gals 1570 NEFE +  3500 pri, may hate  0 bbls 270 Kcl  in 1287 pri; 15 min 641 pri  Return to production.  edge and belief. I further certify that any pit or below-  of an (attached) alternative OCD-approved plan .  DATE 1-4-07
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W  12/27/06 Acidiv  40 ba  6.5 bp  151P-2  Well d  Ran D  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Revin W  For State Use Only	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  Reperfy 6234'-6288' Wl  U sealers AIR 5.9 BPM &  M @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  ead  Mul rods, pump and tly  above is true and complete to the best of my knowle  closed according to NMOCD guidelines , a general permit  TITLE Operation  Lemail address:  Kwidner @ USO	Attach wellbore diagram of proposed completion  W/thy  8000 galy 1570 NEFE +  3500 pri, may rate  O bbly 270 KCI  in 1287 pri; 15 min 641 pri  Return to production.  Edge and belief. I further certify that any pit or below-  or an (attached) alternative OCD-approved plan    DATE 1-4-07  Telephone No. 432-684-9696
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W  12/27/06 Acidiv  40 ba  6.5 bp  151P-2  Well d  Ran D  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Revin W  For State Use Only	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  Reperfy 6234'-6288' Wl  U sealers AIR 5.9 BPM &  M @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  ead  Mul rods, pump and tly  above is true and complete to the best of my knowle  closed according to NMOCD guidelines , a general permit  TITLE Operation  Lemail address:  Kwidner @ USO	Attach wellbore diagram of proposed completion  W/thy  8000 galy 1570 NEFE +  3500 pri, may rate  O bbly 270 KCI  in 1287 pri; 15 min 641 pri  Return to production.  Edge and belief. I further certify that any pit or below-  or an (attached) alternative OCD-approved plan    DATE 1-4-07  Telephone No. 432-684-9696
13. Describe proposed or complete of starting any proposed wo or recompletion.  12/26/06 POOH W  12/27/06 Acidiv  40 ba  6.5 bp  151P-2  Well d  Ran D  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Revin W  For State Use Only	eted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:  Nods and pump, POOH  Reperfy 6234'-6288' Wl  U sealers AIR 5.9 BPM &  M @ 4400 psi Hushed W/30  593; 5 min 1949 psi; 10 mu  ead  Mul rods, pump and tly  above is true and complete to the best of my knowle  closed according to NMOCD guidelines , a general permit  TITLE Operation  Lemail address:  Kwidner @ USO	Attach wellbore diagram of proposed completion  W/thy  8000 gals 1570 NEFE +  3500 pri, may hate  0 bbls 270 Kcl  in 1287 pri; 15 min 641 pri  Return to production.  edge and belief. I further certify that any pit or below-  of an (attached) alternative OCD-approved plan .  DATE 1-4-07