## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

## FILE IN TRIPLICATE

DISTRICT I 1625 N. French Dr., Hobbs, NM 88240

**DISTRICT II** 

1301 W. Grand Ave, Artesia, NM 88210

**DISTRICT III** 

1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION

OIL COMBERTAL	TOTA DI VISION
ICT I 1220 South St. French Dr., Hobbs, NM 88240 Santa Fe, NI	7000
ICT II	5. Indicate Type of Lease
7. Grand Ave, Artesia, NM 88210	STATE X FEE
ICT III	6. State Oil & Gas Lease No.
io Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELL	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR	PLUG BACK TO A North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G101)	for such proposals.) Section 23
e of Well:	8. Well No. 421
Oil Well X Gas Well Other	
ne of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	
iress of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City TX 79323	

DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (Form G)	Section 23	
1. Type of Well:	8. Well No. 421	
Oil Well X Gas Well Other		
2. Name of Operator	9. OGRID No. 157984	
Occidental Permian Ltd.		
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)	
HCR 1 Box 90 Denver City, TX 79323		
4. Well Location		
Unit Letter H : 1650 Feet From The North	330 Feet From The East Line	
Section 23 Township 18-S	Range 37-E NMPM Lea County	
11. Elevation (Show whether DF, RR 3681' KB	(B, RT GR, etc.)	
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT	
PULL OR ALTER CASING Multiple Completion	CASING TEST AND CEMENT JOB	
OTHER:	OTHER: Clean out/acid stimulate	

- 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or ecompletion.
- 1. RUPU. NU BOP. Kill well.
- 2. Pull out of hole with ESP equipment.
- 3. RIH w/bit & tag @4300'. No fill. POOH w/bit.
- 4. RIH w/treating packer set @3954'.

CONDITIONS OF APPROVAL IF ANY

- 5. RU HES & acid treat open hole 3997'-4300' with 3000 gal of 15% HCL acid & 2000# of gelled rock salt. RD HES. Swab back.
- 6. RU pump truck & pump 2000 gal of 6490 chemical w/100 bbl of fresh water. Flush w/500 bbl of 10# brine. POOH w/treating packer.
- 7. RIH w/ESP equipment on 124 its of 2-7/8" tubing. ND BOP. Intake set @3921'.
- 8. RDPU. Clean location

I hereby certify that the information above is true and complete to the best of my knowle	dge and belief. Further certify that any pit or below-grade tank has been/will be
constructed or	F
closed according to NMOCD guidelines , a general permit	or an (attached) alternative OCD-approved
	plan
SIGNATURE / MADE CONTROLL	TITLE Administrative Associate DATE 01/24/2007
TYPE OR PRINT NAME Mendy A Johnson E-mail address:	mendy_johnson@oxy.com TELEPHONE NO. 806-592-6280
For State Use Only	
APPROVED BY Lay W. Wink	TITLE DATE

OC DISTRICT SUPERVISOR/GENERAL MANAGER