Form 3160-5 (April 2004)

## DEPARTMENT OF THE INTERIOR CD-HOBBS

**BUREAU OF LAND MANAGEMENT** 

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No.

If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. LC 031670B

		(, cae p.c	F						
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well  ✓ Oil Well	8. Well Name and No.								
2. Name of Operator Burgundy Oil & Gas of New Mexico Inc.					Burger B-20 #1  9. API Well No.				
3a Address 401 W Texas Ave., Suite 1003,	3b. Phone No. (include 432-684-4033	area code)	30-025-26393  10. Field and Pool, or Exploratory Area						
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					y O&G/Warren Tubb Oil				
1980' FNL & 1980' FWL, Sec. 20, T20S, R38E, UL F					11. County or Parish, State				
				Lea, NM	1				
12. CHECK AF	PPROPRIATE BOX(ES) TO	O INDICATE NATUR	E OF NOTICE, R	EPORT, OR	OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Stance   Reclamation   Recomplete   Temporarily Al   Water Disposal	·	Water Shut-Off Well Integrity Other				
13. Describe Proposed or Complete	ed Operation (clearly state all per	tinent details, including esti-	nated starting date of a	ny proposed woi	rk and approximate duration thereof.				

- If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
  - 1. 25 sx cmt on CIBP @ 5785'
  - 2. 25 sx cmt at base of salt, +/- 2750'
  - 3. 25 sx cmt at top of salt & shoe, 1550'
  - 4. 25 sx cmt @ 400'
  - 5. Surf plug 50' to surface
  - 6. Clean location & install marker

Hole to be loaded w/ 9.5 ppg mud between plugs

## SEE ATTACHED FOR CONDITIONS OF APPROVAL



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)									
Cindy K. Campbell		Title Production Assistant							
Signature Condy K. Compbell		Date 01/04/2007							
THIS SPACE FOR FEDERAL	OR	STATE OFF	CE U	XPI	PRO	VED			
	-								
Approved by		Title		Date					
Conditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.		Office		JA	N 10	2007			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person within	knowingly and willf its jurisdiction.	illy to n	FREE	JERROWEN	WRIENTO NGINEE	f the Un	ited	
(Instructions on page 2)									

## **SUNDRY NOTICE SPECIAL STIPULATIONS**

- 1. Approval is granted to P/A this well with the following modifications to the program:
- 2. The plugs @ 2750' and 1550' must be tagged, for top and bottom of salt.
- \* All plugs, including the surface plug, should be at least 25 sacks of cement and 100 feet.

Engineering can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 1/10/07