

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-05189
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name T. D. POPE 35
8. Well Number 6
9. OGRID Number 227103
10. Pool name or Wildcat DENTON; DEVONIAN (16910)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
PLATINUM EXPLORATION, INC.

3. Address of Operator
550 WEST TEXAS AVENUE, SUITE 500, MIDLAND, TEXAS 79701

4. Well Location

Unit Letter P : 660 feet from the S line and 660 feet from the E line
Section 35 Township 14S Range 38E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3813' KB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil _____ Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER—TEMPORARILY ABANDON ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9-25-06—OPEN WELL TO 0 PSI. ND WH AND RU WL. GIH WITH 5-1/2" GAUGE RING TO 5880'. TAG JUNK AT 5880. GIH WITH CIBP AND SET AT 5880'. LOAD 8-5/8" CASING WITH 300 BBLs WTR. SIW FOR NIGHT.

9-26-06— OPEN WELL TO 0 PSI. PRESSTO 540 PSI. LOST 42 PSI, IN 35 MIN. FINAL PRESS 498 PSI. WITNESSED BY OCD FIELD REPRESENTATIVE E. L. GONZALES WHO ACCEPTED TA AS OK. WELL TEMPORARILY ABANDONED.

This Approval of Temporary
Abandonment Expires 9/26/11

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCGD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE G. J. Rasmussen TITLE VICE-PRESIDENT DATE 01-16-07

Type or print name GREG RASMUSSEN
For State Use Only

E-mail address: RAS@T3WIRELESS.COM Telephone No. 432-687-1664

APPROVED BY: Harry W. Wink TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE _____

Conditions of Approval (if any):

FEB 01 2007