Form 3160-5 (April2004)

## OCD-HOBBS UNITEDSTATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORMAPPROVED OM B No. 1004-0137 Expires: March 31, 2007

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

LC-064118

5. Lease Serial No.

Do not use this	s form for proposals II. Use Form 3160 - 3	to drill or to re-er	nter an posals.	6. If Indian. Allottee or Tribe Name
SUBMIT IN TRIE	7. If Unit or CA/Agreement. Name and/or No.			
1. Type of Well Oil Well	Gas Well Other			8. Well Name and No.
2. NameofOperator Latigo Petroleum, Inc. 3a. Address P.O. Box 10340 Midland	TY 70702 7340	3b. Phone No. (include (432)685-82	· · ·	9. API Well No. 30-025-10963 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec		<u></u>	2.0	Langlie Mattix 7 Rvrs Qn Grayburg
Sec 35 (F), T23S, R37E 1980' FNL & 1980' FWL	11. County or Parish, State Lea NM			
12. CHECK AP	PROPRIATE BOX(ES)T	O INDICATE NATUR	E OF NOTICE, R	EPORT CASH HER 13273
TYPE OF SUBMISSION		TYI	PEOF ACTION	/ <b>12</b>
X Notice of Intent  ☐ Subsequent Report ☐ Final Abandonment Notice	Acidize AlterCasing Casing Repair Change Plans Convert to Injection	Deepen FractureTreat New Construction Plug and Abandon Plug Back	Production (Sta Reclamation Recomplete X Temporarily Ab Water Disposal	and of the second of the secon
If the proposal is to deepen dire  Attach the Bond under which the following completion of the inv	ctionally or recomplete horizon he work will be performed or prolyed operations. If the operational Abandonment Notices shall of final inspection.)	nally, give subsurface location rovide the Bond No. on file on results in a multiple complete filed only after all require	with BLM/BIA. Requipletion or recompletion ements, including reclar	any proposed volk and perturent markers and zones.  The vertical depths of all perturent markers and zones.  The subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once mation, have been completed, and the operator has and ary recovery project.

Set a CIBP @ 3300' & run a MIT.

## SEE ATTACHED FOR CONDITIONS OF APPROVAL

Approved to run MIT
Within 30 days,
Prairie Chicken moting
Season begins 3/5,

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  Lisa Hunt	Title Regulatory Analyst	1			
Signature Lisa Hunt	Date 01/16/2007	APPROVED			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by	Title	Date JAN 2 5 2007			
Conditions of approval, if any, are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	rrant or or or lease Office	WESLEYAW. INGRAM PETROLEUM ENGINEER			

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 505-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 505-234-5972; Lea County 505-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

WWI 11022006