

OCD - H0335

Form 3160-5  
(August 1999)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**SUNDRY NOTICES AND REPORTS ON WELLS**  
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 20005. Lease Serial No.  
22700T LC 064118 - pm

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.


8. Well Name and No.  
Eva Blinebry #19. API Well No.  
30-025-1093610. Field and Pool, or Exploratory Area  
Langlie Mattix 7 rrvs11. County or Parish, State  
Lea, N. Mex.

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- 1) Circulate into Steel Pit. 25 or 35' cmT
- 2) Set C.I.B.P. at 3,250', cap w/ 15 sx cement.
- 3) Circulate Well Bore w/ 10# Salt Gel mud.
- 4) Spot 20<sup>25</sup> sx cement Plug at 2,502".
- 5) Spot 20<sup>25</sup> sx Plug at 1,650', WOC, TAG.
- 6) Spot 110 sx cement Plug from 550' to Surface.
- 7) Install Dry Hole Marker.



CEMENT PLUGS MUST BE MINIMUM 25 SX

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Howard Boatright

Signature

*[Signature]*

Title

Agent

Date

2/5/07

SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GWW

OPERATORS - FOR SUNDRIES  
SUBMIT 1 ORIGINAL AND 5  
COPIES

Latigo Petroleum, Inc  
Ena Blinberry Federal F1

700.7"  
150 ft

13 3/8  
318 ft

7" Cas at 3307  
TOC 150'

OH-3307-3542

Dr4 Hole Marker

20 1/2 x Cmt Plug  
1650 - 1550 Ftg.

20 1/2 x Cmt Plug  
2502 - 2402

CIBP 3250  
+ 15 1/2 x cmt