

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br>30-025-35148  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>VA-1333   |
| 7. Lease Name or Unit Agreement Name<br>Taco AUK State  |
| 8. Well Number<br>2   |
| 9. OGRID Number<br>025575   |
| 10. Pool name or Wildcat<br>Wildcat Atoka   |

|   |  |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)<br>1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other |  |
| 2. Name of Operator<br>Yates Petroleum Corporation  |  |
| 3. Address of Operator<br>105 S. 4 <sup>th</sup> Street, Artesia, NM 88210  |  |
| 4. Well Location<br>Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line<br>Section <u>10</u> Township <u>10S</u> Range <u>34E</u> NMPM <u>Lea</u> County  |  |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.)<br>4197' GR  |  |
| Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>  |  |
| Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____  |  |
| Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____   |  |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: Convert to SWD (SWD-1058) ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P & A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well bore diagram of proposed completion or recompletion.

- 1) MIRU. NDWH and NU BOP. Establish injection rate into Atoka perfs.
- 2) Release packer and TOH w/tubing and packer.
- 3) TIH w/cement retainer and set @ 11300'.
- 4) Squeeze Atoka perfs w/75 sx cement. Have additional 100 sx on standby on location. WOC.
- 5) Drill out retainer and cement. Test squeeze to 1000#. Resqueeze if necessary. Drill out CIBP @ 11695'. Establish injection rate into Morrow perfs.
- 6) TIH w/cement retainer and set @ 11675'.
- 7) Squeeze Morrow perfs w/100 sx cement. Have additional 100 sx on standby on location. WOC.
- 8) Drill out retainer and cement. Test squeeze to 1000#. Resqueeze if necessary. Drill out cement and CIBP @ 12360'. Establish injection rate into Mississippian perfs.
- 9) TIH w/cement retainer and set @ 12350'.
- 10) Squeeze Mississippian perfs w/75 sx cement. Have additional 100 sx on standby on location. WOC.

Continued - Page 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Stormi Davis TITLE Regulatory Compliance Technician DATE 2-12-07

Type or print name Stormi Davis E-mail address: stormid@ypcnm.com Telephone No. 505-748-1471


For State Use Only

APPROVED BY: Harry W. Wink TITLE REGULATORY COMPLIANCE II/STAFF MANAGER DATE FEB 22 2007

Conditions of Approval (if any):

Taco AUK State 2  
30-025-35148  
Lea County, NM

- 11) Drill out retainer and cement. Test squeeze to 1000#. Resqueeze if necessary. Drill out cement and CIBP @ 12860'. Establish injection rate into Woodford perms.
- 12) TIH w/cement retainer and set @ 12850'.
- 13) Squeeze Woodford perms w/75 sx cement. Have additional 100 sx on standby on location. WOC.
- 14) Drill out retainer and cement. Test squeeze to 1000#. Resqueeze if necessary. Drill out CIBP @ 12950'. Drill up to 100' new hole (or as much as practical w/power swivel). Clean hole and TOH.
- 15) Acidize Devonian w/10000 gal 15% NEFE HCl.
- 16) TIH w/plastic-coated packer and plastic-coated tubing. Set packer @ 12920'.
- 17) Perform integrity test and place well in SWD service.

  
Stormi Davis  
Regulatory Compliance Technician  
2-12-07