UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Do not us	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT ORY NOTICES AND REPORTS ON W se this form for proposals to drill or to re ad well. Use Form 3160-3 (APD) for such p	e-enter an	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. NMLCO63798 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well			8. Well Name and No. Bell Lake #19 9. API Well No. 30-025-26275 26257 10. Field and Pool, or Exploratory Area S. Bell Lake Morrow (Gas)
3a. Address P. O.Box 21468, Tulsa, OK 74121-1468 918-491-4314 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			
NW NE (660' FNL & 1980' FEL) of Sec. 12-24S-33E			11. County or Parish, State Lea/NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE TYPE OF SUBMISSION TYPE OF ACTION			PORT, OR OTHER DATA
Notice of Intent Subsequent Report Final Abandonment Notice			Well Integrity Other
Attach the Bond under wh following completion of the testing has been completed determined that the site is	mpleted Operation (clearly state all pertinent details, including es n directionally or recomplete horizontally, give subsurface location the work will be performed or provide the Bond No. on file the involved operations. If the operation results in a multiple complete details of the control of the involved operations. If the operation results in a multiple complete involved operation of the involved operations of the operation of the involved operations. If the operation results in a multiple complete involved operation of the involved operation of the operati	ions and measured and true e with BLM/BIA. Required appletion or recompletion in rements, including reclamat	vertical depths of all perting in markers and zones. subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once

- Check TD to 9500'. Run CBL/GRC/CCL log from 9500-8300.
- Perf Bones Springs @ 9001-9002, 9007-9010, 9013-9016, 9020-9024, 9027-9028, 9035, 9038, 9041-9043 (1 spf).
- Set pkr @ 8900'. Acidize w/1500 g. 15% NEFE + 25 BS. Swab back & test.
- If zone makes an abundance of water, squeeze off using a retainer @ 8995'. Sting into retainer & squeeze w/200 sxs cmt.
- If water production is not acfactor, RIH w/RBP & set @ 8995'.
- Perf @ 8941, 44, 45, 62, 63, 64, 66, 67, 68, 70, 72, 75, 76, 78, 82, & 87 (1 spf).
- Set pkr @ 8850' & acidize w/15% NEFE + 40 BS. Swab test. If zone is wet, POOH w/RBP & set CIBP @ 8900' w/10' cmt on top. Turn well over to Chaparral to test Delaware.

Approximate starting date: 7/1/06. I hereby certify that the foregoing is true and correct APPROVED Name (Printed/Typed) Charlotte Van Valkenburg Title Technical Coordinate 2006 Signature JUL 6/15/06 THIS SPACE FOR FEDERAL OR STATE OFFICE USE LES BABYAK PETROLEUM ENGINEER Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.