Form 3160-5 (April2004)

## UNITEDSTATES

DEPARTMENT OF THE INTERIO CD-HOBBS BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORMAPPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

NM	LC034	71	1
----	-------	----	---

6. If Indian, Allottee or Tribe Name

abandoned we	II. Use Form 3160 - 3	(APD) for such pro	posals.			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			se side.	7. If Unit	or CA/Agreement, Name and/or No	<u>.</u>
1. Type of Well Gas Well Other				8. Well Name and No.		
2. NameofOperator Latigo Petroleum, Inc.				9. API Well No.		
3a. Address       3b. Phone No. (include area code)         P.O. Box 10340 Midland TX 79702-7340       (432)685-8229				30-025-30693  10. Field and Pool, or Exploratory Area <i>DHC 380</i> .  Teague Paddock-Blinebry; Teague Devon		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2310' FSL & 660' FWL SEC 35(L) T23S, R37E				11. County or Parish, State LEA NM		
12. CHECK AI	PPROPRIATE BOX(ES)TO	O INDICATE NATUI	RE OF NOTICE, R	EPORT, O	R OTHER DATA	_
TYPE OF SUBMISSION		TY	PEOF ACTION			<del></del>
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize AlterCasing Casing Repair Change Plans Convert to Injection	Deepen FractureTreat New Construction Plug and Abandon Plug Back	Production (State Reclamation Recomplete Temporarily At Water Disposal	oandon	Water Shut-Off Well Integrity OtherPull plug & DH commingle.	
following completion of the in testing has been completed. Find determined that the site is read 11/16/06 - MIRU. Unsee pump bailer to 7260' & If flow line then kill well. Find 11/17/06 - RIH w/ bull petring. POOH. Pulled a	volved operations. If the operational Abandonment Notices shall by for final inspection.)  at pump. ND tree. Repeat on 4 1/2" cast iron POOH w/ bailer.  Jug, mud anchor, 4' peatl 7/8 rods & 35 3/4 rotel rod string. RIH w/rodel.	on results in a multiple com be filed only after all requir elease TAC. NU E n plug. Fell throug erforated sub, seat ods. SD. Leave of	operation or recompletion or recompletion or recompletion or POOH w/ for to 7516'. Well on to 7516' well on to flow line.	tin a new intermation, have the RU & Pressure C. ND B	ent reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once been completed, and the operator has & RIH w/ chisel point sand ed up. Bleed well down the GOP & NU tree. Run rod commingled the Teague PTED FOR RECORD	<b>)</b> مید
	To the state of th	090 090 1000 1000 1000 1000 1000 1000 1	1		DEC 1 9 2006  LES BABYAK ETROLEUM ENGINEER	
14. I hereby certify that the fore Name (Printed/Typed)	going is true and correct	3005 375 33	İ.,	क्षास्त्रपुर्वा है। सर्वे		
Lisa Hunt	/127	Titig.	Regulatory Ana	alyst	The state of the s	— way
Signature Lisa	Hunt	Title*  Date	12/08/2006			
	THIS SPACE FOR	R FEDERAL OR S	TATE OFFICE	USENA	GE*	<del></del>
Approved by  Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applican  Title 18 U.S.C. Section 1001 and T	al or equitable title to those right to conduct operations thereo itle 43 U.S.C. Section 1212, male	ice does not warrant or hts in the subject lease n.	FEB 2 3 Office		Date  any department or agency of the United	- - -
States any false, fictitious or frau	dulent statements or represent	tations as to any matter w	ithin its jurisdiction.			