Office		State of New Mexico			Form C-103		
District I				WELL ADINO	March 4,	2004	
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-05418				
1301 W. Grand Ave., Artesia, NM 88210	rand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease			
District III	et III 1220 South St. Francis Dr.			STATE	FEE 🗸	ł	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV  Santa Fe, NM 87505			6. State Oil & 0				
1220 S. St. Francis Dr., Santa Fe, NM							
87505 SUNDRY NO	TICES AND REPORT	S ON WELLS		7 Lease Name	or Unit Agreement Nar	ne	
(DO NOT USE THIS FORM FOR PROI	POSALS TO DRILL OR TO	DEEPEN OR PL	UG BACK TO A		· ·		
DIFFERENT RESERVOIR. USE "APP PROPOSALS.)	LICATION FOR PERMIT" (	FORM C-101) FO	OR SUCH	Lovingtor	n Paddock Unit		
1. Type of Well:			8. Well Number				
Oil Well Gas Well Other Injector			57				
2. Name of Operator			9. OGRID Number				
	Mid Continent L.P,						
3. Address of Operator			10. Pool name or Wildcat				
15 Smith Rd, Midland, TX 79705			Lovington Paddock				
4. Well Location							
170% I 24420 F	. 1980 feet from	41. North	1:	695 feet f	rom the West 1	i	
Unit Letter_ E	: 1900 feet from	the North	line and	feet f	from the West 1	ine	
Section 6	Township	17-S R	ange 37-E	NMPM Lea	County	1	
Section	11. Elevation (Sho						
	,			,			
Pit or Below-grade Tank Application (							
Pit Location: UL E Sect 6 Twp	<u>17S Rng 37E</u> Pit type	Steel D	epth to Groundwater	75 Distance from	nearest fresh water well O	ver 1000'	
Distance from nearest surface water_	Below-grade Tani	k Location UL_	SectTv	vpRng	_;		
1980 feet from the north line and							
	x Appropriate Box to INTENTION TO:  ☐ PLUG AND ABAND			BSEQUENT R	EPORT OF:		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE D	RILLING OPNS.	PLUG AND ABANDONMENT	Ø	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A	AND			
OTHER:			OTHER:			П	
	unlated amountions (Cl				atan in aladina antimata		
13. Describe proposed or con of starting any proposed							
		-	ie Completions. 7	Attach wellbore diag		letion	
or recompletion.	å intent 1/31/07		•	•		letion	
or recompletion.  1. Notified Gary Wink with ocd P & A  2. RIH Tag @ CIBP @ 5890': M & F	25sx class c cmt @5890'	2/1/07	Approved a	Attach wellbore diagns sof to bond is retain	he Well Bore 10 1/ 18		
or recompletion.  1. Notified Gary Wink with ocd P & A  2. RIH Tag @ CIBP @ 5890': M & F  3. Tag Toc # 5686': M & P 30 sx Clas	<sup>2</sup> 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07		Approved a	as to plugging of t der bond is retain	the Well Box 17 18	letion	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & P 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq	P 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt	at 2/6/07	Approved a Liability un surface rest	as to plugging of t der bond is retain coration is comple	the Well Boxe, 17 18 med until	letion	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & P 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' squ 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ	P 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt leezed 180 sx class c cmt le 140 sx Class C Cmt down	at 2/6/07	Approved a Liability un surface rest	as to plugging of t der bond is retain coration is comple	the Well Boxe, 17 18 med until	letion	
or recompletion.  1. Notified Gary Wink with ocd P & A  2. RIH Tag @ CIBP @ 5890': M & F  3. Tag Toc # 5686': M & P 30 sx Clas  4. Tag Toc @ 4567' Perf @ 3250' sq  5. Tag toc @ 2725' Perf @ 2200 squ  6. Tag toc @ 1405' Perf @ 450' Circ  7. Cut off & Install Dry Hole Marker	P 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt ueezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07	nt 2/6/07 2/7/07 5 1/2 csg, out F	Approved a Liability un surface rest	as to plugging of t der bond is retain coration is comple 8 ann. to surf 1/8/07 P	the Well Bore 17 18 ned until 2 cted.	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & F 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt ezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07	at 2/6/07 2/7/07 5 1/2 csg, out F	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/	as to plugging of t der bond is retain coration is comple 8 ann. to surf 1/8/07 P	the Well Bore 17 18 ned until 2 ted.	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & F 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt ezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07	at 2/6/07 2/7/07 5 1/2 csg, out F	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/	as to plugging of t der bond is retain coration is comple 8 ann. to surf 1/8/07 P	the Well Bore 17 18 ned until 2 ted.	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & P 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker  I hereby certify that the information grade tank has been/will be constructed	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt ezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07	at 2/6/07 2/7/07 5 1/2 csg, out F	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/	as to plugging of t der bond is retain coration is comple 8 ann. to surf 1/8/07 P lge and belief. I fur or an (attached) alte	the Well Bore 17 18 ned until 2 eted.  2 &A complete 2/8/07 Receive ther certify that any pit onternative Of Dapproved plants.	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & F 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker I hereby certify that the information grade tank has been/will be constructed.  SIGNATURE	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt eezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07  On above is true and con or closed according to NMC	at 2/6/07 2/7/07 5 1/2 csg, out F applete to the beoch guidelines [	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/ est of my knowled , a general permit [ Field Sup	as to plugging of toder bond is retain coration is completed ann. to surf 1/8/07 Pluge and belief. I fur or an (attached) alternation	the Well Box 17 18 ned until eted.  &A complete 2/8/07 Receive ther certify that any pit only renative Octoapproved plan DATE  DATE  DATE	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & P 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker  I hereby certify that the information grade tank has been/will be constructed.  SIGNATURE	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt eezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07  On above is true and con or closed according to NMC	at 2/6/07 2/7/07 5 1/2 csg, out F aplete to the bo	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/ est of my knowled , a general permit [ Field Sup	as to plugging of toder bond is retain coration is completed ann. to surf 1/8/07 Pluge and belief. I fur or an (attached) alternation	the Well Bore 17 18 ned until 2 eted.  2 &A complete 2/8/07 Receive ther certify that any pit onternative Of Dapproved plants.	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & F 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name  Jimmy Ba	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt eezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07  On above is true and con or closed according to NMC	at 2/6/07 2/7/07 5 1/2 csg, out F applete to the beoch guidelines [	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/ est of my knowled , a general permit [ Field Sup	as to plugging of toder bond is retain coration is completed ann. to surf 1/8/07 Pluge and belief. I fur or an (attached) alternation	the Well Box 17 18 ned until eted.  &A complete 2/8/07 Receive ther certify that any pit only renative Octoapproved plan DATE  DATE  DATE	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & F 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name  Jimmy Ba	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt eezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07  On above is true and con or closed according to NMC	at 2/6/07 2/7/07 5 1/2 csg, out F applete to the beoch guidelines [	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/ est of my knowled , a general permit [ Field Sup	as to plugging of toder bond is retain coration is completed ann. to surf 1/8/07 Pluge and belief. I fur or an (attached) alternation	the Well Box 17 18 ned until eted.  &A complete 2/8/07 Receive ther certify that any pit only renative Octoapproved plan DATE  DATE  DATE	letion 19 20 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & P 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker I hereby certify that the information grade tank has been/will be constructed  SIGNATURE  Type or print name  Jimmy Ba  (This space for State use)	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt eezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07  On above is true and con or closed according to NMC	at 2/6/07 2/7/07 5 1/2 csg, out F  applete to the be DCD guidelines [ TITLE  E-mail ad	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/ est of my knowled , a general permit [ Field Sup	as to plugging of the der bond is retain to complete ann. to surf 1/8/07 Pluge and belief. I fur or an (attached) alterervisor	the Well Boxe 17 18 ned until eted.  8.A consiste 2/8/07  ther certify that any pit onto crnative O To approved plant DATE  DATE  DATE  Telephone No. 432-56	19 20 27 19 27 10 27	
or recompletion.  1. Notified Gary Wink with ocd P & A 2. RIH Tag @ CIBP @ 5890': M & F 3. Tag Toc # 5686': M & P 30 sx Clas 4. Tag Toc @ 4567' Perf @ 3250' sq 5. Tag toc @ 2725' Perf @ 2200 squ 6. Tag toc @ 1405' Perf @ 450' Circ 7. Cut off & Install Dry Hole Marker I hereby certify that the information grade tank has been/will be constructed SIGNATURE	2 25sx class c cmt @5890' ss C Cmt @ 4820' 2/2/07 queezed 180 sx class c cmt eezed 180 sx class c cmt 140 sx Class C Cmt down 2/8/07  On above is true and con or closed according to NMC	at 2/6/07 2/7/07 5 1/2 csg, out F  applete to the be DCD guidelines [  TITLE  E-mail ad  TITLE	Approved a Liability un surface rest Perfs Up 5 1/2 X 8 5/ est of my knowled , a general permit [ Field Sup	as to plugging of the der bond is retain to complete ann. to surf 1/8/07 Pluge and belief. I fur or an (attached) alterervisor	the Well Bore, 17 18 ned until eted.  8.A complete 2/8/07 Receive ther certify that any pit only renative Officapproved plan DATE 28/97 Telephone No. 432-56	letion 19 20 27	