OCD-HOBBS

	0					
Form 3160-5 (April 2004)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007		
				5. Lease Serial No.	ga R - pm	
	UNDRY NOTICES AND RE			6. If Indian, Allottee		
Do no abano	t use this form for proposals loned well. Use Form 3160-3	(APD) for such p	roposals.		· · · · · · · · · · · · · · · · · · ·	
	TIN TRIPLICATE- Other ins	tructions on rev	erse side.	7. If Unit or CA/Agree	terment, Name and/or No. A - DM	
1. Type of Well Oil Wel		INjectioNL	VELL	8. Well Name and No		
2. Name of Operator XT	'O Energy, Inc.			9. API Well No.		
3a. Address 200 N. Loraine, St	ie. 800 Midland, TX 79701	3b. Phone No. (inch 432-620-6740	-	30-025-04629 10. Field and Pool, or	Exploratory Area	
	otage, Sec., T., R., M., or Survey Description	01112 1		Eunice Monum		
660 FNL & 660 FW	L, Unit D, Section 14, T-21S, R-36E	89101		11. County or Parish,	State	
		/0	* 2	Lea Co., NM		
12. C	HECK APPROPRIATE BOX(ES) T	GUNDICARE NATI	IRE OF NEXALE R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMI	SSION	N HOPE	YPE OF ACTION			
Notice of Intent	Acidize		Production (St		ter Shut-Off 11 Integrity	
	Alter Casing	Fracture Treat	Recomplete		er Original MIT Chart	
Subsequent Repor	Change Plans	Plug and Abando	Temporarily A	-	sent to OCD	
Final Abandonme	nt Notice Convert to Injection	Plug Back	Water Disposal			
determined that the 11/4/06 MIRU YB, 27 jts BB, 4 Tagged @ 3,88 11/7/06 PU 3-1	repleted. Final Abandonment Notices shall e site is ready for final inspection.) PU. ND WH. NU BOP. RU Bo Monk \$ \$ jts GB & 1 jt RB. LD GB & RB jts. B 0'. /8'' drill bit & BS. RIH on 2-3/8'' WS (Scanalog. POOH w/11 Bull Dog MI & Racked	8 jts of 2-3/8'', 4.7#, J- 4,000' of 2-3/8'', 4.7#,	55, EUE, 8rd IPC tbg. J-55, EUE, 8rd WS. F	Scanalog showed 86 jts U & RIH w/2-3/8'' WS.	
bbls of 8.6# bri Left pkr swing	H w/2-7/8" WS to 3,732'. RU Key pmp ne wtr. Circ hole clean w/100 bbls of 8 ing free @ 3,744'. RIH w/1-11/16" tool nent @ 3,759'. Pmpd 2.5 BW & loaded	.6# brine wtr for 30". s. Found marker sub (BLWTR 250. PU 2-7/8 @ 3.760'. Dropped 1/2'	" inflatable pkr. RIH " setting ball. Let fall f	w/118 jts of 2-3/8" WS.	
15% 90/10 Aci iob TCA press	Loaded tbg w/5 bbls of 8.6# brine & b dTol & 1,550# of rock salt in 5 stages. / ure avg 900 psig. Observed good diver (vac). BLWTR 175. BFL @ 1,400 FFS	Avg BPM 1.6. Pressur t action w/each stage	e avg 1,150 psig. RU p of rock salt. Flushed to	mp trk on backside & btm w/20 bbls of FW	held 1,000 psig during	
Name (Printed	hat the foregoing is true and correct (Typed) y Ward	Title	Regulatory Analyst			
Signature K	ustinard	Date		01/30/2007		
	() THIS SPACE FOI	R FEDERAL OR			FOMADGOUN	
Approved by Lo	up W. Wink 0	C FIELD REPRES	Title	Date		
Conditions of approva certify that the application	I, if any are attached. Approval of this not in holds legal or equitable title to those righ e applicant to conduct operations thereon.	ice does not warrant or	Office	r Eff	1.4 20.	
Title 18 U.S.C. Section States any false, fictition	1001 and Title 43 U.S.C. Section 1212, make us or fraudulent statements or representation	it a crime for any perso ons as to any matter withi	n knowingly and willfull n its jurisdiction.	y to make to any department	RICK WRIGHE Unite EUM ENGINEER	
(Instructions on pa	^{ge 2)} GWW			PETROL		

Eunice Monument So. Unit #356 Acid Stimulation Cont'd.

- 11/10/06 RU swab equip. BFL @ 2,450 FFS. Made 42 swab runs. Rec 135 BW & 0 BO. EFL @ 2,800 FFS. RD swab. Attempted to rel pkr, sheared pkr. Pkr was stuck. RU Key pmp trk on tbg. Pmpd 10 bbls dwn tbg. POOH w/tbg. LD WS & pkr. SWI.
- 11/11/06 RIH w/3-1/8" spear on EOT. Tagged btm @ 3,931'. POOH w/tbg. LD spear. Rec small piece of rubber off of isolation pkr. RIH w/isolation pkr assbly on EOT. Stacked out assbly @ 3,735'. Could not get passed 3,735'. POOH w/tbg. LD BHA. PU 3-1/4" shoe w/cutrite on end. RIH on EOT to top of 4" liner. SWI.
- 11/12/06 RU prod csg. Fin RIH w/3-1/4" shoe to 3,931'. Did not stack out w/tbg in 4" liner @ any point. Worked shoe fr 3,700'-3,800'. POOH w/tbg. LD shoe. SWI.
- 11/14/06 RIH w/pmp valve plug, 4" hydraulic pkr, inj valve, 3 2-1/16" jts of tbg, 4" ASX pkr w/on/off tool & 117 jts of 2-3/8", 4.7#, J-55, EUE, 8rd IPC tbg. RIH w/Gamma Ray & CCL tool. Get on depth w/Dresser Atlas CNL log dated 2/11/87. Set top mechanical pkr at 3,652'. RU pmp trk & chart recorder. Load & tst TCA to 500 psig. Held solid for 30". Load tbg & press up to 600 psig setting top Hydraulic packing element (3,757') & bottom (3,762'). RD pmp trk. Rel on/off tool. Circ TCA w/110 bbls of pkr fluid. SWI
- 11/15/06 ND BOP. Pressd 4" & 5-1/2" TCA to 500 psig for 30" & Performed MIT test for NMOCD, held ok. Pressd 2-3/8" tbg to 1,800 psig & ruptured pmp out plug. RDMO PU. RWTI.

