Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-HOBBS

FORM APPROVED

|   | OMB | No. | 1004-0137 |  |
|---|-----|-----|-----------|--|
| _ |     |     |           |  |

|          |       |     | 12/ |
|----------|-------|-----|-----|
| Expires: | March | 31, | 20  |

NM-85940

| Do not use this fo               | orm for proposals to drill or to re-enter an abandoned well. (APD) for such proposals. |
|----------------------------------|--|
|                                  | SUBMIT IN TRIPLICATE   |
| <ol> <li>Type of Well</li> </ol> |  |

SHADDY MOTICES AND DEDO

| Do not use this form for proposals to different to the second second to the second sec |  |
|--|--|
| Use Form 3160-3 (APD) for such proposals.  | 6. If Indian, Allottee or Tribe Name                         |
| SUBMIT IN TRIPLICATE   | 7 If Unit or CA A  |
| Type of Well     Oil Gas   | 7. If Unit or CA, Agreement Designation                      |
| X   Well   Other   | 0 11111  |
| 2. Name of Operator  | 8. Well Name and No.   |
| STRATA PRODUCTION COMPANY  | Urraca Federal #3  |
| 3. Address and Telephone No P. O. Box 1030   | 9. API Well No.<br>30-025-37687                              |
| Roswell, NM 88202-1030 505-622-1127  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  | 10. Field and Pool, or Exploratory Area Diamondtail Delaware |
| 1980' FSL & 660' FWL   | 11. County or Parish State                                   |

| 1980' FSL & 660' FWL  |   |  |   |  |  |
|---|---|--|---|--|--|
|   |   |  |   |  |  |
|   | ~   | L  | ea County, New Mexico   |  |  |
| RIATE BOX(s) TO INDICAT   | <b>TE NATURE OF NOTIC</b>                                       | E, REPORT, OR OTHER  | DATA  |  |  |
|   |   |  |   |  |  |
| Acidize  Alter Casing  Casing Repair  Change of Plans  Convert to Injection | Deepen Fracture Treat New Construction Plug & Abandon Plug Back | Production (Start/Resun<br>Reclamation<br>Recomplete<br>Temporily Abandon<br>Water Disposal              | Water Shut-Off Well Integrity Other Comp  |  |  |
|   | Acidize Alter Casing Casing Repair Change of Plans              | Acidize Deepen Alter Casing Fracture Treat Casing Repair New Construction Change of Plans Plug & Abandon | Acidize Deepen Production (Start/Resun Alter Casing Repair New Construction Recomplete Change of Plans Plug & Abandon Temporily Abandon |  |  |

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RU Schlumberger Wireline. TIH & set CIBP at 7671', 20' above top perf. Dump 35' cmt on plug. TIH w/4" csg guns. Perf D zone as follows: 7403', 04', 05', 06', 11', 12' & 13' (7 holes). Perf D1 zone as follows: 7444', 45', 46', 47', 48', 53', 54', 55', 56' & 57' (10 holes). SISD. PU pkr. TIH /w tbg. Set tbg at 7460'. Spot 2 bbls 7 1/2% NeFe across perfs. PU set pkr at 7338'. RU. Pump 58 bbls 7 1/2% NeFe w/34 ball sealers. Frac D and D1 zones via 5 1/2" csg. Pumped 23,459# of Lite Prop 125 14/30 sand. TIH w/production string. Tag up at 7655'. Set TA. Build wellhead. PU pump. TIH w/ 171 rods. Seat pump. Space out rods. Hung well on w/good pump action.

| 1234  | Kon Kala<br>Top                               | 18 18 20 21/2                   |                         |                |              |          |
|---|---|---------------------------------|-------------------------|----------------|--------------|----------|
| 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  | 27282872                                      | <del>***</del>                  |                         | <del></del>    |              |          |
| 17  | Z12926272                                     | Title                           | Production              | Records        | 3            | RECORD   |
| Signature THIS SPACE FO   | OR FEDERAL OF                                 | Date                            | 02/21/07                | TACCE          | PTEDFO       | RRECORU  |
| Approved by   | Title   | TOTALE                          | Date                    | 1700           |              | 5 2007   |
| Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.  Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, m. United States any false, fictitious or fraudulent statements or representations. | Office  |                                 |                         | 1              | $-\eta_{AM}$ |          |
| Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, m. United States any false, fictitious or fraudulent statements or representations.  | ake it a crime for any pentations as to any m | person knowing atter within its | ngly and willfully to n | nake to any de | PARTE DE LE  | y of the |

Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## OCD-HOBBS

FORM APPROVED OMB No. 1004-0137

| BUREAU OF LAND MAN   | NAGEMENT  |  |   | Expires: March 31, 2007  |  |  |
|--|---|--|---|--|--|--|
| CUMPRY MOTIOTO AND DED   | 5. Lease Serial No.   |  |   |  |  |  |
| SUNDRY NOTICES AND REPO  | NM-85940  |  |   |  |  |  |
| Do not use this form for proposals to drill or to re<br>Use Form 3160-3 (APD) for such proposals.  | -enter an abandone  | ea well.   |   | 6. If Indian, Allottee or Tribe Name                                 |  |  |
| SUBMIT IN TRI  | IPLICATE  |  |   | 7. If Unit or CA, Agreement Designation                              |  |  |
| 1. Type of Well Oil Gas  |   |  |   |  |  |  |
| X Well Well Other  |   |  |   | 8. Well Name and No.   |  |  |
| 2. Name of Operator  |   | · /  |   | Urraca Federal #3  |  |  |
| STRATA PRODUCTION 3. Address and Telephone Nc P. O. Box 1030   | ON COMPAN   | Υ  |   | 9. API Well No. 30-025-37687   |  |  |
| Roswell, NM 88202-1  | 1030 505-622-1  | 1127   |   | 10. Field and Pool, or Exploratory Area                              |  |  |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description  |   |  |   | Diamondtail Delaware   |  |  |
| 1980' FSL & 660' FV  | NL  |  |   | 11. County or Parish, State  |  |  |
| Section 11-T23S-R32E   | <b>=</b>  |  |   | Lea County, New Mexico   |  |  |
| 12. CHECK APPROPRIATE BOX(s) TO IND  | ICATE NATURE C  | F NOTICE, I  | REPORT, OR OTH  |  |  |  |
| TYPE OF SUBMISSION   | *****   | TYPE OF  |   |  |  |  |
| Notice of Intent Acidize Alter Casing  | Deepen<br>Fracture Trea   | =  | Production (Start/Re  | esume) Water Shut-Off Well Integrity                                 |  |  |
| X Subsequent Report Casing Repair  | New Construc  | ction F  | Recomplete  | Other Comp   |  |  |
| Change of Plans  | Plug & Aband  | lon 7  | emporily Abandon  |  |  |  |
| Final Abandonment Notice Convert to Injection  | n Plug Back   |  | Vater Disposal  |  |  |  |
|  |   |  |   |  |  |  |
| following completion of the involved operations. If the operation testing has been completed. Final Abandonment Notices shall be determined that the site is ready for final inspection.)  RU Schlumberger Wireline. TIH & set D zone as follows: 7403', 04', 05', 06', 46', 47', 48', 53', 54', 55', 56' & 57' (10 2 bbls 7 1/2% NeFe across perfs. PU ball sealers. Frac D and D1 zones via TIH w/production string. Tag up at 768 Seat pump. Space out rods. Hung we SEE ATTACHED FUR CONDITIONS OF APPROXIMATIONS OF APPROXIMATI | : CIBP at 7681'.<br>11', 12', & 13'<br>holes). SISD.<br>set pkr at 7338<br>5 1/2" csg. Pu<br>55'. Set TA. B | . 20' of cn<br>(7 holes).<br>PU pkr. 7<br>3'. RU. Pu<br>umped 23,<br>uild wellhe | nt on top. TIH v<br>Perf D1 zone a<br>FIH w/tbg. Set<br>ump 58 bbls 7 1<br>459# of Lite Propagation | w/4" csg guns. Perf<br>as follows: 7444', 45',<br>tbg at 7460'. Spot |  |  |
| 14. I hereby certify that the foregoing is true and correct  | <del></del>   |  | - \2<br>2   | 8 3  |  |  |
| Name (Printed/Typed) Kelly M. Brjtt  |   |  | े∂<br>Production Reco   |  |  |  |
| 1/14 224 / 144   |   |  |   | orus   |  |  |
|  | FOR FEDERAL OF  |  | 2/02/07   |  |  |  |
| THIS SPACE   | Title   | n STATE UP   | Date Date   |  |  |  |
| Approved by  |   | -  |   |  |  |  |
| Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.  | Office  |  |   |  |  |  |

## SUNDRY NOTICE SPECIAL STIPULATIONS

- 1. Approval is granted for the plug backs with the following stipulations:
- 2. A minimum of 35' of bailed cement or 50' of pumped cement is required on top of a CIBP when perfs are abandoned and the CIBP must be set within 100' of the top perf.

Engineering can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 2/16/07