## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-07430	
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NO	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreen	nent Name
	ROPOSALS TO DRILL OR TO DEEPEN APPLICATION FOR PERMIT" (Form G		North Hobbs (G/SA) Unit Section 29	
Type of Well:  Oil Well X	Gas Well Other		8. Well No. 221	
2. Name of Operator			9. OGRID No. 157984	_
Occidental Permian Ltd.  3. Address of Operator	· · · · · · · · · · · · · · · · · · ·		10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	<u>C 79323</u>			110003 (0/0/1)
Unit Letter F : 2310	Feet From The North		t From The West	Line
Section 29	Township 18-S	Range 38-E	, NMPM	Lea County
S. West Edition	11. Elevation (Show whether DF, RI 3653' DF	KB, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Chec	k Appropriate Box to Indicate Na		Other Data SEQUENT REPORT OF	
PERFORM REMEDIAL WORK		REMEDIAL WORK		
	PLUG AND ABANDON		ALTERING	=
TEMPORARILY ABANDON X	CHANGE PLANS	COMMENCE DRILLING OPN		BANDONMENT
PULL OR ALTER CASING  OTHER:	Multiple Completion	CASING TEST AND CEMENT OTHER:	I JOB []	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion:				
1 Vill and Dell Con and and			430	
<ol> <li>Kill well. Pull ESP equipment.</li> <li>Run bit &amp; scraper to 4213'.</li> </ol>			/.j/	<b>3</b>
3. Set CIBP @4100'. Test casing to	1000 PSI.		N N	
<ul><li>4. Cap plug with ±10' of cement.</li><li>5. TA well &amp; install TA wellhead.</li></ul>				9 <del>5</del> 5
5. TA well & fistall TA wellnead.				
			132	<b>"</b>
				e de la companya de La companya de la co
I hereby certify that the information above is	true and complete to the best of my know	ledge and belief. Ifurther certify t	hat any pit or below-grade tank h	as been/will be
constructed or closed according to NMOCD guidelines	<del></del>	<b>-</b>		
Toolea according to revious guidelines	, a general permit	or an (attached) alternative plan	ось арріочец	
SIGNATURE Mency	of Claphmar	TITLE Administrative	Associate DATE	03/20/2007
TYPE OR PRINT NAME Mendy A. 3	obnson E mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only	1. 1: 1			
CONDITIONS OF APPROVAL IF ANY:	J.WWK.	OC HELD REPRESENTA	DAT	E <u>MAR 2 7 20</u> 07
GWW			WOLVE I. WELVECT	<b>學展</b>