Submit 3 Copies 10 Appropriate District	State of N	lew Mexico	For	rm C-103
Office District I	Energy, Minerals a	nd Natural Resources	M	fay 27, 2004
1625 N. French Dr., Hobbs, NM 88240	237		WELL API NO.	
Vistrict II 301 W. Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION		30- 041-20932		
1301 W. Grand Ave., Artesia, NM 88210	1220 South St. Francis Dr.		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE	
District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOT	ICES AND REPORTS ON	WELLS	7. Lease Name or Unit Agreeme	nt Nama
(DO NOT USE THIS FORM FOR PROPO			7. Lease Name of Omit Agreeme	in Name
DIFFERENT RESERVOIR. USE "APPLI	· · · · · · · · · · · · · · · · · · ·		West Todd	/
PROPOSALS.)			West rodu	
1. Type of Well: Oil Well 🔲	Gas Well Other	- And	8. Well Number #1	
		MARINA 19 2001		
2. Name of Operator		MAR 19 200 HM	9. OGRID Number	
CHI OPERATING, INC		MATT METERS		
3. Address of Operator		\ oco /	10. Pool name or Wildcat	
PO BOX 1799 MIDLAND, TX	79702			
4. Well Location				
Unit Letter I: 1980	feet from the	SOUTH line and 990	feet from theWEST	line
Section 29 Towns			County Roosevelt	
Section 29 Towns		ether DR, RKB, RT, GR, etc		
		-4224'; KB-4236'		
Pit or Below-grade Tank Application		1221, 110 1230	+ · · · · · · · · · · · · · · · · · · ·	
Pit type Depth to Groundw		est fresh water well Di	stance from nearest surface water	
				_
Pit Liner Thickness: mil	Below-Grade Tank: Volu	me bbls; (Construction Material	
12. Check	Appropriate Box to Ind	icate Nature of Notice	, Report or Other Data	
		1		
NOTICE OF IN			BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO	RK 🔲 ALTERING CA	ASING 🗌
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR COMMENCE DF	RK	ASING 🗆
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WO	RK	ASING []
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR COMMENCE DR CASING/CEMEN	RK	ASING []
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORD COMMENCE DR CASING/CEMEN OTHER:	RK	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly seems)	REMEDIAL WOR COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as	RK	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or compost of starting any proposed we	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly seems)	REMEDIAL WOR COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as	RK	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly seems)	REMEDIAL WOR COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as	RK	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For	REMEDIAL WOR COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as r Multiple Completions: A	RK	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280 ', Letter the component of the compon	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For logged wellbore, Ran 4 ½" p	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as r Multiple Completions: A	RK ALTERING CARILLING OPNS. P AND A NT JOB Ind give pertinent dates, including est Attach wellbore diagram 34 proposed	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280 ', Le POZ:GEL + .25#/sx CF. Tail w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For logged wellbore, Ran 4 ½" p	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as r Multiple Completions: A	RK	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280 ', Letter the component of the compon	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For logged wellbore, Ran 4 ½" p	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as r Multiple Completions: A	RK ALTERING CARILLING OPNS. P AND A NT JOB Ind give pertinent dates, including est Attach wellbore diagram 34 proposed	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280 ', Le POZ:GEL + .25#/sx CF. Tail w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For logged wellbore, Ran 4 ½" p	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as r Multiple Completions: A	RK ALTERING CARILLING OPNS. P AND A NT JOB Ind give pertinent dates, including est Attach wellbore diagram 34 proposed	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280 ', Le POZ:GEL + .25#/sx CF. Tail w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For logged wellbore, Ran 4 ½" p	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as r Multiple Completions: A	RK ALTERING CARILLING OPNS. P AND A NT JOB Ind give pertinent dates, including est Attach wellbore diagram 34 proposed	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280 ', Le POZ:GEL + .25#/sx CF. Tail w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For logged wellbore, Ran 4 ½" p	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as r Multiple Completions: A	RK ALTERING CARILLING OPNS. P AND A NT JOB Ind give pertinent dates, including est Attach wellbore diagram 34 proposed	timated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING TEMPORARILY ABANDON DULL OR ALTER CASING TEMPORARILY ABANDON DULL OR ALTER CASING TEMPORARILY ABANDON DESCRIPTION OF STATEMENT OF THE STATEMENT OF	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" p. 1/300 sxs "C" + .2% FL-25,	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as removed completions: A corod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC-	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including est Attach wellbore diagram of proposet 1.6#. Cmtd Lead w/1100 sxs Color. 1.0 hrs, ND, set slips, cut off, chan in	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Le POZ:GEL + .25#/sx CF. Tail we pits, released rig 3/4//07.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pr/300 sxs "C" + .2% FL-25, above is true and complete	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as an Multiple Completions: A corod. csg, N80 11.6#/J55 11 Circ w/140sxs t/pit. WOC-	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including estattach wellbore diagram of proposet 1.6#. Cmtd Lead w/1100 sxs Control 1.6#. Cmtd Lead w/11	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Le POZ:GEL + .25#/sx CF. Tail we pits, released rig 3/4//07.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pr/300 sxs "C" + .2% FL-25, above is true and complete	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as an Multiple Completions: A corod. csg, N80 11.6#/J55 11 Circ w/140sxs t/pit. WOC-	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including est Attach wellbore diagram of proposet 1.6#. Cmtd Lead w/1100 sxs Color. 1.0 hrs, ND, set slips, cut off, chan in	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Le POZ:GEL + .25#/sx CF. Tail we pits, released rig 3/4//07.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pr/300 sxs "C" + .2% FL-25, above is true and complete closed according to NMOCD gu	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as an Multiple Completions: A corod. csg, N80 11.6#/J55 11 Circ w/140sxs t/pit. WOC-	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including estattach wellbore diagram of proposet 1.6#. Cmtd Lead w/1100 sxs Control 1.6#. Cmtd Lead w/11	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Le POZ:GEL + .25#/sx CF. Tail we pits, released rig 3/4//07.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly stork). SEE RULE 1103. For logged wellbore, Ran 4 ½" provided with the second sec	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as removed completions: A corod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC-	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including est Attach wellbore diagram 34 proposed 1.6#. Cmtd Lead w/1100 sxs **C** 1.0 hrs, ND, set slips, cut off, and the company of the compan	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Lemporaries Pozicial we pits, released rig 3/4//07. I hereby certify that the information grade tank has been will be constructed er SIGNATURE: Type or print name: ROBIN ASI	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly stork). SEE RULE 1103. For logged wellbore, Ran 4 ½" provided with the second sec	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, and multiple Completions: A corod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC-	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including est Attach wellbore diagram 34 proposed 1.6#. Cmtd Lead w/1100 sxs **C** 1.0 hrs, ND, set slips, cut off, and the company of the compan	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Lemporaries Pozicial we pits, released rig 3/4//07. I hereby certify that the information grade tank has been will be constructed er SIGNATURE: Type or print name: ROBIN ASI	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly stork). SEE RULE 1103. For some second wellbore, Ran 4 ½" progress with the second secon	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, and multiple Completions: A corod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC-	RK ALTERING CARILLING OPNS. P AND A NT JOB P AND A NT JOB Proposed attach wellbore diagram of proposed 1.6#. Cmtd Lead w/1100 sxs C 1.0 hrs, ND, set slips, cut off, can be ge and belief. I further certify that any or an (attached) alternative OCD-approx DATE: 3/9/07	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Lempoz:GEL + .25#/sx CF. Tail we pits, released rig 3/4//07. I hereby certify that the information grade tank has been/will be constructed er SIGNATURE: Type or print name: ROBIN ASIFOR State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pri/300 sxs "C" + .2% FL-25, above is true and complete relosed according to NMOCD gu TITLE: R KEWE-mail addre	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as a Multiple Completions: A prod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC- to the best of my knowled, a general permit CREGULATORY CLERK	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including estattach wellbore diagram of proposed 1.6#. Cmtd Lead w/1100 sxs. Control 2.#. Control 2	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Lemporaries Pozicial with the pozicial with the pits, released rig 3/4//07. I hereby certify that the information grade tank has been will be constructed en SIGNATURE: Type or print name: ROBIN ASING State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pri/300 sxs "C" + .2% FL-25, above is true and complete relosed according to NMOCD gu TITLE: R KEWE-mail addre	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as a Multiple Completions: A prod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC- to the best of my knowled, a general permit CREGULATORY CLERK	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including estattach wellbore diagram of proposed 1.6#. Cmtd Lead w/1100 sxs. Control 2.#. Control 2	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Lemporaries Pozicial with the pozicial with the pits, released rig 3/4//07. I hereby certify that the information grade tank has been will be constructed en SIGNATURE: Type or print name: ROBIN ASING State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pri/300 sxs "C" + .2% FL-25, above is true and complete relosed according to NMOCD gu TITLE: R KEWE-mail addre	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as a Multiple Completions: A prod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC- to the best of my knowled, a general permit CREGULATORY CLERK	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including estattach wellbore diagram of proposed 1.6#. Cmtd Lead w/1100 sxs. Control 2.#. Control 2	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Lempoz:GEL + .25#/sx CF. Tail we pits, released rig 3/4//07. I hereby certify that the information grade tank has been/will be constructed er SIGNATURE: Type or print name: ROBIN ASIFOR State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pri/300 sxs "C" + .2% FL-25, above is true and complete relosed according to NMOCD gu TITLE: R KEWE-mail addre	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as a Multiple Completions: A prod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC- to the best of my knowled, a general permit CREGULATORY CLERK	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including estattach wellbore diagram of proposed 1.6#. Cmtd Lead w/1100 sxs. Control 2.#. Control 2	timated date completion 50:50:10 up & jet
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilled 7 7/8" hole to 4280', Lemporaries Pozicial with the pozicial with the pits, released rig 3/4//07. I hereby certify that the information grade tank has been will be constructed en SIGNATURE: Type or print name: ROBIN ASING State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly sork). SEE RULE 1103. For ogged wellbore, Ran 4 ½" pri/300 sxs "C" + .2% FL-25, above is true and complete relosed according to NMOCD gu TITLE: R KEWE-mail addre	REMEDIAL WORD COMMENCE DE CASING/CEMEN OTHER: state all pertinent details, as a Multiple Completions: A prod. csg, N80 11.6#/J55 11. Circ w/140sxs t/pit. WOC-	ALTERING CARILLING OPNS. P AND A NT JOB Indigive pertinent dates, including estattach wellbore diagram of proposed 1.6#. Cmtd Lead w/1100 sxs. Control 2.#. Control 2	timated date completion 50:50:10 up & jet