## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

## Revised 5-27-2004 FILE IN TRIPLICATE OIL CONSERVATION DIVISION **DISTRICT I** 1220 South St. Francis Dr. WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-07410 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease 1301 W. Grand Ave, Artesia, NM 88210 STATE FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd, Aztec, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G101) for such proposals.) Section 27 1. Type of Well: 8. Well No. 131 Oil Well X Gas Well Other 2. Name of Operator 9. OGRID No. 157984 Occidental Permian Ltd. Address of Operator 10. Pool name or Wildcat Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4. Well Location Unit Letter L 1650 Feet From The South Feet From The Line 412 West Section Range Township 18-S 38-E **NMPM** Lea County 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3638' KB Pit or Below-grade Tank Application or Closure Pit Type \_\_\_\_\_ Depth of Ground Water Distance from nearest fresh water well \_\_\_\_\_\_ Distance from nearest surface water Below-Grade Tank: Volume \_\_\_\_ Pit Liner Thickness \_ mil \_\_ bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. X **PLUG & ABANDONMENT** PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB OTHER: Deepen/Run CNL/Run Liner/Perf/AT OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. This Notice of Intention C-103 amends form dated 01/30/2007. Well is to be deepened, 5-1/2" FJ liner ran & perforated. 1. Kill well. NU BOP. 2. POOH w/RBP's @2036' & 3879'. 3. Clean out well to TD @4252'. 4. Set CIBP @3975'. Top w/cement. Squeeze hole from 1975' to 3975'. 5. Drill out cement to CIBP. Deepen well to new TD @4300'. 6. Run 5-1/2" FJ liner from 4300' to surface. 7. RU CNL/GR/CCL log from PBTD to ±3300'. 8. Perforate hole. 9. Acid treat well. Run scale squeeze. 10. RIH w/ESP equipment and return well to production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative OCD-approved plan

**SIGNATURE** TITLE Administrative Associate DATE 03/22/2007 TYPE OR PRINT NAME Mendy Johnson E-mail address: TELEPHONE NO. mendy johnson@oxy.com 806-592-6280

For State Use Only

APPROVED BY

TO DICTUIC THE LIBERVISOR / GENERAL MANAGER

conditions of approval if any: Med Top of Cement on 5/2" FT lines!

MAR 2 8 2007