Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSERVATION DIVISION		30-025-30702
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
District IV	Salita Fe, INIVI 67303		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOT	ICES AND REPORTS ON WELLS	3	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PL	UG BACK TO A	Lowe
DIFFERENT RESERVOIR. USE "APPLI	"APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)	Cas Well Cother		8. Well Number 1
1. Type of Well: Oil Well	ATT THE TOTAL CONTRACTOR OF THE PARTY OF THE		
2. Name of Operator		9. OGRID Number	
Paladin Energy Corp.			164070
3. Address of Operator			10. Pool name or Wildcat
10290 Monroe Drive, Suite 301, I	Dallas, Texas 75229		King Wolfcamp
4. Well Location			
Unit Letter M	: 900 feet from the South	line and _5	feet from the <u>West</u> line
Section 25	Township 13-S	Range 37-E	NMPM Lea County
Section 23	11. Elevation (Show whether DR		
3845'			
Pit or Below-grade Tank Application or Closure			
	Distance from nearest fresh water well_	Distance from near	est surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material Synthetic			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK 🔀 PLUG AND ABANDON 🗌 REMEDIAL WORK 🔲 ALTERING CASING 🗌			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	R ALTER CASING		
OTHER:			olfcamp perforations
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
R/U pulling unit, GIH with bit a	nd work string. Drill out and rec	cover CIBP's at 9,	790' and at 10,084'. Clean and circulate
hole. Tag plugback TD at 11,970'. Re-acidize Wolfcamp perforations at 10,119-140', 9,856-990'. Swab back and test.			
Place well on rod pump and resi	ume production.	314101017	
hole. Tag plugback TD at 11,970'. Re-acidize Wolfcamp perforations at 10,119-140', 9,856-990'. Swab back and test. Place well on rod pump and resume production.			
15 200 LS			
	/4°	Br D V	
	(2)		
		1296	
	**	05 628210	
I haraby partify that the information	n shove is true and complete to the l	nest af my knowledo	ge and belief. I further certify that any pit or below-
grade tank has been/will be constructed (r above is true and complete to the torrelate according to NMOCD guidelines	. a general permit .	or an (attached) alternative OCD-approved plan .
	U .		
SIGNATURE CONTRACTOR	and TITLE	VP Exploration &	Production DATE 3/8/2007
Type or print name David Plaisa	nce E-mail address: d	plaisance@paladine	nergy.com Telephone No. 214-654-0132
For State Use Only			
OC FIELD REPRESENTATIVE ILISTABLE MANNACES			
APPROVED BY: Haww. Wang Of FIELD REPRESENTATIVE 11/STAFF MANAGEM DATEDATE			
Conditions of Approval (if any):			MAR 2 9 2007
* * * * * * * * * * * * * * * * * * * *			MAK 2 4 71111/