Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
District II		30-025-03882	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE 7 FEE	
District IV Santa Fe, NM 8/303		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			
87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Established of Sint Light Sint Linux
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			West Lovington Unit
PROPOSALS.)			8. Well Number
1. Type of Well: Oil Well Gas Well 7 Other Injector		#21	
2. Name of Operator		9. OGRID Number 241333	
Chevron Mid Continent L.P,			
3. Address of Operator			10. Pool name or Wildcat
15 Smith Rd, Midland, TX 79705			lovington Upr San Andres W.
4. Well Location			
Unit Letter : 1980 feet from the South line and 660 feet from the East line			
Unit Letter :	reet from the	inie and	rect from theinte
Section 5	Township 17-S	ange 36-E	NMPM Lean 13 County 70
Section	11. Elevation (Show whether D.		
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)			
Pit Location: UL 1 Sect 5 Twp 17S Rng 36E Pit type Steel Depth to Groundwater 65 Distance from nearest rest water well of 1000			
1980 feet from the SOUTH line and	1000 feet from the East line (	Steel Lank)	(2)
			100 07 223
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK		REMEDIAL WOR	
PERFORM REMEDIAL WORK	FEOG AND ABANDON	INCIVILDIAL WOR	ALTERNITO GAGINO
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.□ PLUG AND ☑
			ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	ND
	COMPLETION	CEMENT JOB	
OTHER:	П	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
	ork). SEE RULE 1103. For Muiti	pie Compietions: Ai	tach wellbore diagram of proposed completion
or recompletion.	1	Διονο	roved as to plugging of the Well Bore.
			ility under bond is retained until
3. Displace hole w/MLF 9.5# Brine w/12.5# gel P/BBL			•
4. Spot 50sx class c Cmt plug from 3234'-2750 tag @ 2794' surface restoration is completed. 5. spot 50 sx cement plug from 2234-1754 tag @ 1796'			
6. Cement plug from 400' surface 13 3/		squeez 250 sx tag @ s	urf
7. Install Dry Hole Marker 3/21/07	3,	.,	
I hereby certify that the information	above is true and complete to the	best of my knowledg	e and belief. I further certify that any pit or below-
			or an (attached) alternative OCD-approved plan .
		Managar	2/24/07
SIGNATURE	TITLE_	Manager	DATE3/21/07
Type or print name Jimmy Bag	(a)	1.1	m 1 1 37 422 564 9600
Type or print name Validation Bag	E-mail a	adress:	Telephone No. 432-561-8600
(TPL:			
(This space for State use)	0		
Approximation of the state of t		in in the state of	A STATE OF THE STA
APPROVED BY Hay W.	Umb JUMEB	EPRESENTATIVE II	WINTER PROPERTY.
Conditions of approval, if any:			MAR 3 C 2007
			9 ~ 400/