

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-23852
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: STATE L
8. Well Number 2
9. OGRID Number
10. Pool name or Wildcat VACUUM

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator CHESAPEAKE OPERATING, INC.
3. Address of Operator P.O. BOX 548806 OKLAHOMA CITY, OK 73154
4. Well Location Unit Letter L : 2,310 feet from the SOUTH line and 330 feet from the WEST line Section 19 Township 17S Range 36E NMPM County IEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3,898'
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE ☐
OTHER: ☐
Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1-31-07 Set 5 1/2" CIBP @8,750'. Cap w/35' cmt. w/bailer. Circ. hole/mud. Spot 25 sx. cmt. @6,250'. Perf 4 holes @3,250'. 2-1-07 Set pkr. @2,920'. Sqz. 50 sx. cmt. No Tag. Sqz. 50 sx. cmt. @3,250'. Tag plug @3,102'. 2-2-07 Perf. 4 holes @2,950'. Set pkr. @2,610'. Sqz 50 sx. cmt. Perf. 4 holes @ 1,940'. Set pkr. @1,550'. Sqz. 50 sx. cmt. No tag. Sqz 50 sx. cmt. @1,940'. 2-5-07 Tag TOC @ 1,686'. Perf 4 holes @390'. Sqz. 50 sx. cmt. w/2% CaCl. Dis. TOC to 270'. Had communication out 5 1/2" X 8 5/8" & 13 3/8" annulus. Tag TOC @265'. Perforate @100'. Circulate 60 sx. cmt. down 5 1/2" csg. thru perfs. w/cmt. Circ. to surface out 5 1/2" X 8 5/8" csg. & out 8 5/8" X 13 3/8" csg. Remove wellhead & anchors. Install P & A Marker. Backfill Collar.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Randall Minear TITLE P & A Supv. DATE 2-20-07
E-mail address: _____ Telephone No. 432-530-0907

Type or print name RANDALL MINEAR

For State Use Only

APPROVED BY Larry W. Wink
Conditions of Approval, if any:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE Feb 20 2007