Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		May 27, 2004
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-36080 5. Indicate Type of Lease
District III	1220 South St. Francis Dr.		STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Steve's Hopper "25"
PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other			8. Well Number 1
2. Name of Operator DAVID H. ARRINGTON OIL & GAS INC			9. OGRID Number 5898
3. Address of Operator PO BOX 2071 MIDLAND, TX 79702			10. Pool name or Wildcat Big Dog; Strawn NW
4. Well Location			big bog, strawn tw
Unit Letter I : 1980 feet from the S line and 660 feet from the E line			
Section 25	Township 15S	Range 34E	NMPM CountyLea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4031' GR			
Pit or Below-grade Tank Application _ or Closure _			
Pit typeDepth to Ground			tance from nearest surface water
110 1000 10000	nil Below-Grade Tank: Volun		onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A Image: Commence drilling opns PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB Image: Commence drilling opns			
OTHER:		OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 			
03/13/07 - 03/27/07: P&A well as follows: Plugging procedures wittnessed by NMOCD representative Maxey Brown. RIH w/ gauge ring to 11500', RIH w/ CIBP set @ 11500' & cap w/ 35' cmt. Circ w/ 270 bbls 12.5# mud. Spot 25 sx cmt plug @ 9708' btm 9450' top, displace w/ 37 bbls 12.5# mud. Circ mud & spot 25 sx cmt plug @ 7360' btm 7110' top. EOT @ 5834', pump 30 sx cmt plug across shoe 5834' btm 5514' top. WOC 4 hrs, RU Rotary WL to cut csg, RIH w/ jet cutter & cut @ 3200'. LD 73 jts 5 1/2" csg. RIH circ w/ 12.5# mud & spot 30 sx cmt plug @ 3259' btm 3132' top. WOC 3 hrs, RIH tag @ 3132'. Circ mud & spot 30 sx cmt plug @ 1926' btm 1800' top, POOH reverse out cmt. Spot 30 sx cmt plug @ 546' btm 413' top, WOC. RIH tag @ 413', pull up to 40' & spot 10 sx cmt plug to surface. Dig out and cut off well head, deadman & anchors. Weld on P&A marker and clean Location.			
			1017128293037 45675128293037 1017121314919 101712111111111111111111111111111111111
			P 13
Liability under bond is retained until			
surface restoration			28 29 30 37 4 1000 10
surrace restoration	a companya		Re 1128
			1. 1. 3. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
			64575757575757575
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].			
signature politic	o home	TLEENGINEER TECH	DATE 03/28/2007
Type or print name DEBBIE FREEMAN E-mail address: DEBBIE@ARRINGTONOIL. Collythone No. (432)682-6685			
For State Use Only			
APPROVED BY: Law W. Wink TITLE DAMAR 3 0 2007 Conditions of Approval (if any):			