Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u>	Energy, Minerals and Natural Reso	urces May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	OH, GOVGERVA WOOM DANIES	WELL API NO. 30-025-38065
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISI	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE 🛛 FEE 🗌
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLI	SALS TO DRILL OR TO DEEPEN OR PLUG BACK T CATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number
2. Name of Operator	bob Energy Corporation	9. OGRID Number 14049
3. Address of Operator	boo Energy Corporation	10. Pool name or Wildcat
PO Box 2	27, Artesia, NM 88211-0227	Corbin Delaware West
4. Well Location	OCE Coat Coard the North Lin	and 1650 feet from the West 15-
Unit Letter C	865feet from theNorth line Township 18S Range 33:	
Section 23	Township 18S Range 33: 11. Elevation (Show whether DR, RKB, RT	
	3893' GL	, GR, cic.y
Pit or Below-grade Tank Application	or Closure 🗌	
Pit typeDepth to Groundv	vaterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction Material
12. Check	Appropriate Box to Indicate Nature of	Notice, Report or Other Data
NOTICE OF IN	ITENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		IAL WORK ALTERING CASING
TEMPORARILY ABANDON	_	ENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	S/CEMENT JOB
OTHER:	☐ OTHER	: Recompletion
	oleted operations. (Clearly state all pertinent	letails, and give pertinent dates, including estimated date
13. Describe proposed or comp	pleted operations. (Clearly state all pertinent	
13. Describe proposed or composed of starting any proposed w	oleted operations. (Clearly state all pertinent oork). SEE RULE 1103. For Multiple Comple	letails, and give pertinent dates, including estimated date
13. Describe proposed or composed of starting any proposed wor recompletion. Recompleted in the Delaw	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Complease zone as follows:	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion
 13. Describe proposed or composed of starting any proposed wor recompletion. Recompleted in the Delaw 2/20/07 – Set CIBP @ 890 	oleted operations. (Clearly state all pertinent oork). SEE RULE 1103. For Multiple Comple	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion
13. Describe proposed or composed of starting any proposed wor recompletion. Recompleted in the Delaw 2/20/07 – Set CIBP @ 890 2/21/07 – Acdz perfs @ 56 2/23/07 – Frac w/ 1987 bb	oleted operations. (Clearly state all pertinent cork). SEE RULE 1103. For Multiple Compleare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' size of 55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPM	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion of '(32 shots). M. AIP – 1674#, ISIP – 1530#.
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 56 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' states and 5 % HCl. Is fluid & 101089# proppant. AIR – 35.4 BPM 0'. Perf the Delaware Sand 2 @ 5364' – 5372'	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion 0' (32 shots). M. AIP – 1674#, ISIP – 1530#.
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion of the completion of th
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion of the completion of th
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion of the completion of th
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date ections: Attach wellbore diagram of proposed completion of the completion of t
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date ections: Attach wellbore diagram of proposed completion of the completion of t
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date ections: Attach wellbore diagram of proposed completion of the completion of t
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion of the completion of th
13. Describe proposed or composed was or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 560 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 560 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53	oleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' w/ 500 gal NE Fe 7 ½% HCl of 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl	details, and give pertinent dates, including estimated date ections: Attach wellbore diagram of proposed completion of the completion of t
of starting any proposed we or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 56 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 500 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53 3/2/07 - Frac w/ 1144 bbls 3/5/07 - Tag sand @ 5356 3/6/07 - Hang well on pun	ork). SEE RULE 1103. For Multiple Completate are zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' or 188'. Set @ wrong depth my mistake. Drill out 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl. fluid & 100200# proppant. AIR – 25 BPM, 2'. Clean out sand to 5600'. Drill out CIBP @ opp.	details, and give pertinent dates, including estimated date ections: Attach wellbore diagram of proposed completion O' (32 shots). M. AIP – 1674#, ISIP – 1530#. O' (27 shots). AIP – 1372#, ISIP – 1225#, 1510 17 18 79 5600'. AIP – 1372#, ISIP – 1225#, 1510 17 18 79 600'. Knowledge and belief. Nurther certify that are not or below-
of starting any proposed w or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 56 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 500 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53 3/2/07 - Frac w/ 1144 bbls 3/5/07 - Tag sand @ 5356 3/6/07 - Hang well on pun	bleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' or 188'. Set @ wrong depth my mistake. Drill out 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl. fluid & 100200# proppant. AIR – 25 BPM, 2'. Clean out sand to 5600'. Drill out CIBP @ or 1997. The same of the best of my closed according to NMOCD guidelines \(\text{\t	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion O' (32 shots). M. AIP – 1674#, ISIP – 1530#. O' (27 shots). t CIBP @ 5008' & push to 5600'. Set @ 5600'. AIP – 1372#, ISIP – 1225#, 1617 1879 Section of the control of th
13. Describe proposed or compostarting any proposed wor recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 56 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 500 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53 3/2/07 - Frac w/ 1144 bbls 3/5/07 - Tag sand @ 5356 3/6/07 - Hang well on pun I hereby certify that the information grade tank has been/will be constructed of	bleted operations. (Clearly state all pertinent cork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' sold Salve Set @ wrong depth my mistake. Drill out 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl. fluid & 100200# proppant. AIR – 25 BPM, 2'. Clean out sand to 5600'. Drill out CIBP @ pp. above is true and complete to the best of my reloced according to NMOCD guidelines , a general TITLE Production	details, and give pertinent dates, including estimated date ections: Attach wellbore diagram of proposed completion O' (32 shots). M, AIP – 1674#, ISIP – 1530#. O' (27 shots). It CIBP @ 5008' & push to 5600'. Set @ 5600'. AIP – 1372#, ISIP – 1225#, 1516-17-18-78 Section of the permit of th
of starting any proposed w or recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 56 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 500 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53 3/2/07 - Frac w/ 1144 bbls 3/5/07 - Tag sand @ 5356 3/6/07 - Hang well on pun	bleted operations. (Clearly state all pertinent cork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' sold Salve Set @ wrong depth my mistake. Drill out 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl. fluid & 100200# proppant. AIR – 25 BPM, 2'. Clean out sand to 5600'. Drill out CIBP @ pp. above is true and complete to the best of my reloced according to NMOCD guidelines , a general TITLE Production	details, and give pertinent dates, including estimated date ections: Attach wellbore diagram of proposed completion O' (32 shots). M, AIP – 1674#, ISIP – 1530#. O' (27 shots). AIP – 1372#, ISIP – 1225#, 1617 1879 Solutions Knowledge and belief. Nurther certify that any phror below- I permit or an (attached) alternative QCB phroved plan . Analyst
13. Describe proposed or compostarting any proposed wor recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 56 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 500 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53 3/2/07 - Frac w/ 1144 bbls 3/5/07 - Tag sand @ 5356 3/6/07 - Hang well on pun I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Diana J. Bit For State Use Only	bleted operations. (Clearly state all pertinent of ork). SEE RULE 1103. For Multiple Completations are zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPM 0'. Perf the Delaware Sand 2 @ 5364' – 5372' 88'. Set @ wrong depth my mistake. Drill out 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl. fluid & 100200# proppant. AIR – 25 BPM, 2'. Clean out sand to 5600'. Drill out CIBP @ app. above is true and complete to the best of my closed according to NMOCD guidelines \(\bar{\text{q}} \), a general address: production ggs	details, and give pertinent dates, including estimated date extions: Attach wellbore diagram of proposed completion O' (32 shots). M, AIP – 1674#, ISIP – 1530#. O' (27 shots). It CIBP @ 5008' & push to 5600'. Set @ 5600'. AIP – 1372#, ISIP – 1225# 1510 1718 78 18 19 19 19 19 19 19 19 19 19 19 19 19 19
13. Describe proposed or compostarting any proposed wor recompletion. Recompleted in the Delaw 2/20/07 - Set CIBP @ 890 2/21/07 - Acdz perfs @ 56 2/23/07 - Frac w/ 1987 bb 2/26/07 - Set CIBP @ 500 2/27/07 - Tag CIBP @ 500 2/28/07 - Acdz perfs @ 53 3/2/07 - Frac w/ 1144 bbls 3/5/07 - Tag sand @ 5356 3/6/07 - Hang well on pun I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	bleted operations. (Clearly state all pertinent cork). SEE RULE 1103. For Multiple Completare zone as follows: 0'. Perf the Delaware Sand 1 @ 5655' – 5670' s55' – 5670' w/ 750 gal NE Fe 7 ½% HCl. Is fluid & 101089# proppant. AIR – 35.4 BPN 0'. Perf the Delaware Sand 2 @ 5364' – 5372' sold Salve Set @ wrong depth my mistake. Drill out 64' – 5372' w/ 500 gal NE Fe 7 ½% HCl. fluid & 100200# proppant. AIR – 25 BPM, 2'. Clean out sand to 5600'. Drill out CIBP @ pp. above is true and complete to the best of my reloced according to NMOCD guidelines , a general TITLE Production	details, and give pertinent dates, including estimated date extions: Attach wellbore diagram of proposed completion O' (32 shots). M, AIP – 1674#, ISIP – 1530#. O' (27 shots). It CIBP @ 5008' & push to 5600'. Set @ 5600'. AIP – 1372#, ISIP – 1225# 1510 1718 78 18 19 19 19 19 19 19 19 19 19 19 19 19 19