UNITEDSTATES DEPARTMENT OF THE INTERIOR OCD-HOBBS

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORMAPPROVED
OM B No. 1004-0137
Expires: March 31, 2007

)	•	L	e	a	S	е	5	e	1	1	aı	 •	i	0	•	
_		_	_			_	_		_		_		_			

N	Ν	1	Ν	I	M	-9	0	1	6	1
---	---	---	---	---	---	----	---	---	---	---

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160 - 3 (APD) for si	uch proposals.								
SUBMIT IN TRIPLICATE - Other instructions or	7. If Unit or CA/Agreement, Name and/or No.								
1. Type of Well Gas Well Other	8. Well Name and No.								
2. NameofOperator	Hawk B-1 #64								
Apache Corporation	9. API Well No.								
	o. (include area code) 30-025-38199								
6120 S Yale Ave, Suite 1500 Tulsa OK 74136-4224 (918)	491-4864 10. Field and Pool, or Exploratory Area								
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Eunice; Blinebry-Tubb-Drinkard, N								
Unit I, 2605' FSL and 1210' FEL, S 9, T 21S, R 37E	11. County or Parish, State Lea, NM								
12. CHECK APPROPRIATE BOX(ES)TO INDICATE	NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF ACTION								
Acidize Deepen Production (Start/Resume) Water Shut-One Recomplete X Subsequent Report Change Plans Plug and Abandon Plug Back Water Disposal Water Shut-One									
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 03/06/07 Perf Drinkard @ 6500-04, 58-62, 78-82, 94-98, 6622-28, 44-48, 66-70 w/ 2 JSPF. 03/07/07 Acidize Drinkard w/3000 gals 15% HCI. 03/08/07 Frac Drinkard w/39K gals gel and 62K # 20/40 sand. 03/09/07 Perf Tubb @ 6114-18, 42-48, 6238-42, 54-58, 6322-26 w/ 2 JSPF. 03/12/07 Set RBP @ 6362. Acidize Tubb w/3000 gals 15% HCI. 03/13/07 Frac Tubb w/36K gals gel and 82K # 20/40 sand. 03/14/07 Perf Blinebry @ 5660-66, 86-90, 5730-36, 5746-50, 5806-10, 5828-32 w/ 2 JSPF. 03/15/07 Set RBP @ 5872. Acidize Blinebry w/3000 gals 15% HCI. 03/21/07 POH RBP's. 03/22/07 RIH w/ pump and rods. 03/22/07 RIH w/ pump and rods. 03/23/07 Set 640 pumping unit. Put on production Blinebry/Tubb/Drinkard.									
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 									
Sophie Mackay	Title Engineering Tech								
Signature Sophie Mackey	Date 04/03/2007								
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for at States any false, fictitious or fraudulent statements or representations as to any	lease Office MAN OFFICE NORTH OF THE PROPERTY OF THE United								