Submit 3 Copies To Appropriate District Office	State of New Mickleo		Form C-103	
District I Energy, Minerals and Natural Resources		ral Resources		Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-20010	
District III 1220 South St. Francis Dr.			5. Indicate Type of Lease	
1000 Rio Brazos Rd Aztec NM \$7410			STATE FEE	
District IV States File State States Santa Fe, NM 87505		1303	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ND REPORTS ON WELLS		7 Lesse Name or I	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			State 35	
PROPOSALS.)		-	8. Well Num	her
1. Type of Well:			#3	
Oil Well 🛛 Gas Well 🗌 Other				
2. Name of Operator			9. OGRID Number	
Penroc Oil Corp			17213	
3. Address of Operator			10. Pool name or Wildcat	
PO Box 2769 Hobbs, New Mexico 88241			Corbin Abo	
4. Well Location				
Unit Letter L 165	feet from theSouth	line and330_	feet from the	line
				-
	Township 17S Range		PM Lea	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
••	priate Box to Indicate N	•	•	
NOTICE OF INTEN	TION TO:	SUBS	EQUENT REP	PORT OF:
PERFORM REMEDIAL WORK 🔲 PLU	G AND ABANDON 🛛	REMEDIAL WORK		ALTERING CASING
	_		_	· · · · ·
TEMPORARILY ABANDON		COMMENCE DRILI		PLUG AND
PULL OR ALTER CASING		CASING TEST AND		ABANDONMENT
	TIPLE	CEMENT JOB		•
		CEMENT COD		:
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.	_	-		
11 3/4" Casing set 334ft, Cement Circulat	ed		1	h, SEP 2003 TAIS
8 5/8" Casing set 4045ft, Cement with 555 sacks Cement			120263031	h 2003 5
4 1/2" Casing set 8793ft, Cement with 450sack Cement				
Plug from 6412-4547ft through Collapsed casing				
Run tubing to 4547ft and Displace well w	vith 9.5# gelled brine water		12/	
Pull tubing			2/	40005 ED 50
Cut and pull 4 ½" casing from 4045ft		.*		0JJ 55 53 54 52
Run tubing to 4095ft, Spot 50 sack ceme				
Run tubing and tag cement plug, Pull to			ubing to 384ft, Ci	rculate cement to
surface, Cut off well head and install PA	marker. Clean and level l	ocation for release		
		-		· .
I hereby certify that the information above	is true and complete to the by	est of my knowledge	and belief.	· · ·
$\bigcap a b b a$		10 1. 1	<u> </u>	011-5-
SIGNATURE by a Dukalb	TITLE	Iminis Iral	un list.	DATE <u>4-11-03</u>
Type or print name JOY A. BUHALTS	E-mail ad	aress: 1 pu Naltse	notmail.com Tele	phone No. 505 - 492 - 1136
(This space for State use)		REPRESENT	• • •	CED
4 1 1		REPRESENTATIVE		
APPPROVED BY Jacque. Le	MR. TITLE_		I	DATE 2003
Conditions of approval, if any		THE COMMISSIO	U WI IST RE NOTIF	IED 24
N				
		PLUGGING OPER	ATIONS FOR THE	C-103
:		TO BE APPROVEE		
		IN DE ALLE	~ •	

. در ا