

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION

1220 South Francis Dr.
Santa Fe, NM 87505
UCD

WELL API NO.

30-025-33388

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

L-5467

7. Lease Name or Unit Agreement Name

Pawnee APW State

8. Well Number

1

9. OGRID Number

025575

10. Pool name or Wildcat

Wildcat Grayburg, Wildcat San Andres
Reeves; Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other P&A

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street, Artesia, NM 88210

4. Well Location

Unit Letter A : 660 feet from the North line and 660 feet from the East line
Section 20 Township 18S Range 35E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3932' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Steel Depth to Groundwater N/A Distance from nearest fresh water well N/A Distance from nearest surface water N/A

Pit Liner Thickness: N/A mil Below-Grade Tank: Volume N/A bbls; Construction Material N/A

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P & A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-27-07 MIRU plugging equipment. TOOH w/production equipment.

3-31-07 Set 5-1/2" CIBP @ 5075'. Dumped 35' cement on top. Set 2nd CIBP @ 4650'. Dumped 35' cement on top.

4-2-07 Set 3rd CIBP @ 4310'. Dumped 35' cement on top. Circulated plugging mud. PUH and spotted 25 sx @ 3843'. PUH and spotted 40 sx @ 3031'. POOH and WOC.

4-3-07 RIH and tagged @ 2713'. POOH. RIH to 1843' and spotted 25 sx. WOC. Tagged @ 1718'. PUH to 400'. Spotted 25 sx. POOH. RIH and perforated @ 60'. Circulated 45 sx cement to surface.

4-4-07 Installed marker and cleaned location.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

WELL IS PLUGGED AND ABANDONED. FINAL REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Stormi Davis TITLE Regulatory Compliance Technician DATE 4-12-07

Type or print name Stormi Davis E-mail address: stormid@ypcnm.com Telephone No. 505-748-1471

For State Use Only

APPROVED BY: Gay W. Wink TITLE REGULATORY REPRESENTATIVE II/STAFF MANAGER DATE APR 18 2007

Conditions of Approval (if any):