	Farm C 102
Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resour	rces Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 District III OIL CONSERVATION DIVIS 1220 South St. Francis Dr.	ION <u>30-025-04641</u> 5. Indicate Type of Lease
District III1220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BA DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUG PROPOSALS.)	ACK TO A CH Eunice Monument South Unit
1. Type of Well: Oil Well Gas Well Other Injection	8. Well Number 388
2. Name of Operator	9. OGRID Number
XTO Energy, Inc.	005380 10. Pool name or Wildcat
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701	Eunice Monument: Grayburg San Andres
4. Well Location	
Unit Letter <u>H</u> : 1980 feet from the North line and <u>660</u> feet from the <u>East</u> line	
Section 15 Township 21S Range	36E NMPM County Lea
11. Elevation (Show whether DR, RKB,	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest strate water	
Pit Liner Thickness: mil Bełow-Grade Tank: Volumebbls	
	of Notice, Report or Other Data SUBSEQUENT REPORTOF: AL WORK ALTERING CASING NCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING COMPLETION CASING	TEST AND
OTHER: OTHER:	Acid Stimulation
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>	
2/27/07 MIRU pumgping PU. ND WH. NU BOP. Rel inj pkr. POOH w/6 jts of 2-1/16" IPC/EPC J-55 tbg, dual	
<pre>isolation pkr assembly, and 116 jts of 2-3/8" IPC 4.70#, j-55, EUE 8rd tbg. 2/28/07 MI &amp; rack 1,000' of 2-3/8" WS w/turned-dwn collars &amp; 3,000' of 2-3/8" WS. PU &amp; RIH w/Sonic Hammer tool on 2-3/8" WS to 3,700'. MIRU acidizing &amp; pmp services. Loaded tbg w/20 bbls 8.6# brine. Sonic Hammer washed perfs from 3,754'-3,967' w/200 bbls of 8.6# brine wtr. Circ hole clean w/50 bbls of 8.6# brine for 30". Sonic Hammered perfs from 3,820'-3,967' w/3,000 gals of 20% NEFE. Flushed acid to btm w/20 BW. RD pmp trk. RU swab equip. Made 5 swab runs. Rec 22 bbls of wtr &amp; 0 BO. Showed little gas w/each run. EFL @ 1,600 FFS.</pre>	
I hereby certify that the information above is true and complete to the best of my grade tank has been/mill be constructed, or closed according to NMOCD guidelines, a ge	
SIGNATURE Histy Ward TITLE Regulatory Analyst DATE 04-03-07	
Type or print name Kristy ward E-mail address: kristy ward@xtoenergy.com Telephone No. 432-620-6740	
APPROVED BY Law Dink TITLE DATE DATE DATE	
Conditions of Approval, if my:	

\$

## Eunice Monument South Unit #388 WIW Acid Stimulation Cont'd.

- 3/1/07 MIRU pmp truck. Pmpd 25 bbls pkr fluid down csg. RIH w/pmp valve plug, 1 2-1/16" jt of tbg, 4" hydraulic pkr, 3 2-1/16" jts of tbg, 4" ASX mech pkr w/on/off tool, 117 jts & 28' of subs of 2-3/8", 4.7#, N-80, EUE, 8rd IPC tbg. RIH w/Gamma Ray & CCL tool. Set top mechanical pkr at 3,731'. Load & test TCA to 500 psig. Load tbg & press up to 600 psig setting top hydraulic packing element (3,824') & bottom (3,829'). Circ TCA w/110 bbls of pkr fluid. ND BOP. NU WH. Pressed 4" & 5-1/2" TCA to 580 psig for 30".
- 3/3/07 PU flange 18 inches off wellhead to put tension in tbg and on/off tool. Pressed 2-3/8" tbg to 1,700 psig & ruptured pmp out plug. RDMO PU. RWTI.



