Form 3160-5 (April 2004)

OCD-HOBBS UNITED STATES

DEPARTMENT OF THE INTERIOR

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				5. Lease Serial No. LC-062300 6. If Indian, Allottee or Tribe Name		
						SUBMIT IN TRIPLICATE- Other instructions on reverse side.
1. Type of Well Gas Well X Other					8. Well Name and No.	
2. Name of Operator				Cotton Draw Unit #96		
Pogo Producing Company				9. API Well No.		
3a. Address		3b. Phone No. (include	area code)	30-025-	37594	
P. 0. Box 10340, Midland, TX 79702 432-685-8100				10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Paduca Delaware		
10' FSL & 1150' FWL, Section 15, T25S, R32E				1	or Parish, State nty, NM OTHER DATA	
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OR	OTHER DATA COSTO	
TYPE OF SUBMISSION		TYP	E OF ACTION		12	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Statement of Statement of Statem	pandon	Water Shut-Off Well Integrity Other drig operations	
		nent details, including estin	nated starting date of a	ny proposed wo	rk and approximate duration thereof. s of all pertinent markers and zones.	

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud & Set Surface Csg - MIRU Capstar #9. Spud well @ 18:00 hrs 01/12/06. Drld 12-1/4" hole to 840'. TD reached @ 11:45 hrs 01/13/06. Ran 18 its 9-5/8" 36# J-55 ST&C csg. Cmt'd w/ 300 sks 65:35 POZ C @ 13.0 ppg followed by 200 sks Cl C + 2% CaCl2 @ 14.8 ppg. Circ 90 sks to surface. Plug down @ 20:00 hrs 01/13/06. WOC 20-1/2 hrs. Make cut-off. Weld on WH. NU BOP & test to 2000#.

Intermediate Csg - Drld 8-3/4" hole to 4950. TD reached @ 04:30 hrs 01/22/06. Logged well w/ Schlumberger. Ran 23 jts 7" 23# J-55 LT&C csg. Cmt 1st stage w/ 300 sks Cl C + add @ 14.09 ppg. Cmt 2nd stage w/ 1000 sks Cl C 50:50:10 @ 11.9 ppg followed by 100 sks Cl C + 2% CaCl2 @ 14.8 ppg. Plug down @ 21:30 hrs 01/23/06. Circ 230 sks to surface. Make cut-off. Install WH. Well shut-in pending TA approval.

The foregoing was done in anticipation of conducting a tertiary (CO2) recovery program in which this well would potentially be used as either an injection well or producing oil well. Given the scarcity of CO2 at this time, our plans have been delayed until such time as an adequate supply of CO2 is secured. Accordingly, Pogo requests that such well be allowed to remain in a TA'd status, with the understanding that it will ACCEPTED FOR RECORD conduct a mechanical integrity test in such well within the next few days.

	· · · · · · · · · · · · · · · · · · ·	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		APR 1 8 2007
Cathy Wright	Title Sr. Eng Tech	ATT 10 2007
Signature Cally Ullight	Date 03/28/07	LES BABYAK
	EDERAL OR STATE OFFICE USE	PETROLEUM ENGINEER
Approved by Lay W. Wink of	IELD REPRESENTATIVE IL/STAFF MAN	MAY 0 7 2007
Conditions of approval, if any, are attached. Approval of this notice do certify that the applicant holds legal or equitable title to those rights in	pes not warrant or	

which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United

(Instructions on page 2,