Submit 3 copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103	
Revised 1-1-89	,

Sistrict Office						
DISTRICT I	OIL CONSERV	ATI(ON DIVISION	WELL API NO.		
P.O. Box 1980, Hobbs, NM 88240	P.O. B	ox 2088	3		30-025-22451	
Santa Fe, New Mexico 87504-2088			5. Indicate Typ			
P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III					STATE 🗸	FEE
1000 Rio Brazos Rd., Aztec, NM 87	410			6. State Oil / G	B-1113-1	
	NOTICES AND REPORTS OF	N WEL	LS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.				7. Lease Name or Unit Agreement Name		
				CENTRAL VACUUM UNIT		
Oll	GAS -	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		1		
1. Type of Well: WELL WELL	WELL OTHER					
2. Name of Operator				8. Well No.	118	/
	ON USA INC			O. Dool Name	or Wildoot	
3. Address of Operator 15 SMI	TH RD, MIDLAND, TX 79705			9. Pool Name VAC	or Wildcat UUM GRAYBURG SAN ANDR	ES
Well Location						
Unit LetterN	: 990 Feet From The	SOUT	TH Line and 1650	Feet From	The WEST Line	
Continue 6	T 189	_	Panas 35F NA	ADM	LEA COUNT	Y
Section 6				A11 1A1		
	10. Elevation (Show whether	DF, RKB,	RT,GR, etc.) 3977' GL			
1. Che	ck Appropriate Box to Indica	ate Nat	ure of Notice, Report	, or Other D	Pata	
NOTICE OF INTER	NTION TO:		SI	JBSEQUE	NT REPORT OF:	
	PLUG AND ABANDON		REMEDIAL WORK	V	ALTERING CASING	
PERFORM REMEDIAL WORK	CHANGE PLANS		COMMENCE DRILLING OP	_	PLUG AND ABANDONMEN	
TEMPORARILY ABANDON			CASING TEST AND CEME		,	
PULL OR ALTER CASING				_	RFS, ACIDIZE	V
OTHER:			OTHER:	0,012	11 0, 7000 E	
4-05-07: MIRU. 4-06-07: PU BIT. TIH W/136 JTS 4-09-07: TIH W/TBG. TAG @ 472 EOT @ 3640. 4-10-07: TIH W/TBG @ 4711. DR 4-11-07: TIH W/NEW BIT, DC'S, 4-12-07: TIH W/GR, CCL. LOG FI 4-13-07: ACIDIZE LOWER SAN & 4-16-07: REL PKR. TIH & TAG @ 4-17-07: PU MJ, TBG, PERF SUE 4-18-07: TIH W/PMP & RODS. 4-19-07: RIG DOWN. FINAL REF	23. DRY DRILL. WORK DN TO 47 CILL 4737 TO 4763. PUMP 10 BBL TBG @ 3640. TIH W/TBG @ 4760 R PBTD @ 4774 TO 2950. PERF ANDRES PERFS 4489-4756 W/47 Q 4677. INSTL BIW. WASH TO PE 3, SN, & TAC.	33. HAF .S DN TI D. DRILL 4736-47 '80 GAL	2D DRILLING. FELL DN @ BG. PULL 6 STANDS. EC . FR 4763-4775. FELL OU 40, 4749-4756, 4704-08, 4 S 15% FERCHEK.	OT @ 4400. IT OF CMT @ 4718-20, 4722 EOT @ 1221.	4778.	
I hereby certify that the information above is true and SIGNATURE	complete to the best of my showledge and belief. TITLE	Regi	ulatory Specialist	1 - MAGE - 11 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	DATE <u>4/27/200</u>	7
						687-7375
TYPE OR PRINT NAME	Denise Pinkerton					

APPROVED LONG OF APPROVAL IT ANY