

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03269
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Xeric Oil & Gas Corporation		6. State Oil & Gas Lease No. E-1922
3. Address of Operator P. O. Box 352 Midland, TX 79702		7. Lease Name or Unit Agreement Name: West Pearl Queen Unit
4. Well Location Unit Letter K : 1980 feet from the South line and 1980 feet from the West line Section 32 Township 19S Range 35E NMPM Lea County		8. Well No. 159
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3717' GL		9. Pool name or Wildcat Pearl Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

- 1) MIRU Pulling Unit.
- 2) Circulate hole w/+/- 60 bbls mud.
- 3) Spot 25 sx of Class C cement on top of CIBP @ 4600'.
- 4) Perforate @ 1700' & squeeze 50' in & out. Tag @ 1650'.
- 5) Perforate @ 150' & squeeze 50' out and circulate to surface.
- 6) Circulate 10 sx Class C cement @ 60' to surface.
- 7) RD. Install dry hole marker & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 9/10/03  
Type or print name Angie Crawford Telephone No. 432-683-3171

(This space for State use)

APPROVED BY Harvey W. Wink TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE SEP 15 2003  
Conditions of approval, if any:

XERIC OIL & GAS CORP.  
WELLBORE DIAGRAM

WELL: West Pearl Queen #159

COUNTY: Lea

STATE: NM

HOLE SIZE: 17"  
CASING: 13 3/8" @ 105'  
CEMENTED WITH: 80<sup>3</sup>x  
CEMENT TOP: Surf.

TUBING: \_\_\_\_\_  
RODS: \_\_\_\_\_  
PUMP: \_\_\_\_\_  
PACKER: \_\_\_\_\_

Liner:  
Size: 4 1/2" w/ 400 gal  
From: 4705' to 5020'

HOLE SIZE: 8"  
CASING: 7" @ 4701  
CEMENTED WITH: 100<sup>3</sup>x  
CEMENT TOP: 3112'

