

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Xeric Oil & Gas Corporation

3. Address of Operator

P. O. Box 352
Midland, TX 79702

4. Well Location

Unit Letter I : 2310 feet from the South line and 990 feet from the East line

Section 31

Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3720' GL

WELL API NO.

30-025-20114

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

E-1638

7. Lease Name or Unit Agreement Name:

West Pearl Queen Unit

8. Well No.

157

9. Pool name or Wildcat

Pearl Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) MIRU Pulling Unit.
- 2) Circulate hole w/+ 60 bbls mud.
- 3) Spot 25 sx of Class C cement @ 4000'.
- 4) Perforate @ 1700' & squeeze 50' in & out. Tag @ 1650'.
- 5) Perforate @ 150' & squeeze 50' out and circulate to surface.
- 6) Circulate 10 sx Class C cement @ 60' to surface.
- 7) RD. Install dry hole marker & clean location.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 9/10/03

Angie Crawford

Type or print name

432-683-3171

Telephone No.

(This space for State use)

APPROVED BY Hayden Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any

DATE

SEP 15 2003

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: West Pearl Queen #157

COUNTY: Lea

STATE: NM

HOLE SIZE: 17 1/2"
CASING: 13 3/8" @ 105'
CEMENTED WITH: 100SX
CEMENT TOP: Surface

Perf @ 150'

Perf @ 1700'

TUBING: _____
RODS: _____
PUMP: _____
PACKER: _____

PERFS:
4086' - 92'

LINER:
SIZE: 4 1/2" w/ 75SX
FROM: 4679' TO: 4992'

CIBP @ 4670' w/ 35' cement

HOLE SIZE: 8"
CASING: 7" @ 4794'
CEMENTED WITH: 125SX
CEMENT TOP: 2950'

PBTD: 5004

TD: 5004

4770' - 4891'

