New Menico Calaba and result to Make a and table to 1625 N. French Drive

Hobbs, NM 88240

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No. NMNM 080123

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name

	THE COUNTY OF TH					
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other			WEST CAP QUEEN SAND UNIT 8. Well Name and No.			
2. Name of Operator PALISADES ASSET HOLDING COMPANY., LLC					WELL NO 15 9. API Well No.	
3a. Address 3b. Phone No. (include area code 432-686-7159		area code)	30-005-01108 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					CAPROCK QUEEN	
330 FNL & 330 FEL SECTION 21, TOWNSHIP 14 SOUTH, RANGE 31 EAST, UNIT LETTER A					11. County or Parish, State CHAVES CO., NEW MEXICO	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
✓ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal		Water Shut-Off Well Integrity Other	
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and gones.						

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

TO PLACE ON PRODUCTION:

- 1) MI & RU SERVICE RIG
- 2) CHANGE OUT DOWNHOLE PUMP & REPLACE BAD RODS
- 3) TEST TUBING
- 4) RERUN DOWNHOLE PUMP & RODS
- 5) PLACE ON PRODUCTION

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)						
HERBERT F. BOLES	Title MANAGING MEMBER					
Signature Derbert L. Bol	Date	04/23/2007				
ACCEPTED FOR FRESTORS FOR FEDERAL OR STATE OFFICE USE						
Approved by /\$/ DAVID R. GLASS		Accepted For Record Only! Approval Subject To Returning Well To Continuous Production And Keeping Well On Continuou				
Conditions of approval 1. The sache to propose of this notice does not want certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	ease E					
		Production Or Plugging Well With An				
Title 18 J.S.C. Section (1995) The 45 J.S. Section 1212, make it a crime for an States any false, factitions of tangentian statements or representations as to any matter.	er within	Approved Plugging Program!				
(Instructions on page 2)						