Submit 3 Copies To Appropriate District State of New Mexico	Form C-103 May 27, 2004						
<u>District I</u> <u>Internal De Habba NM 88240</u> Energy, Minerals and Natural Resources	WELL API NO.						
1625 N. French Dr., Hobbs, NM 88240 District II	30-025-26494						
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease						
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410	STATE 🗌 FEE 🛛						
District IV Salita Fe, NW 87505	6. State Oil & Gas Lease No.						
1220 S. St. Francis Dr., Santa Fe, NM							
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	V F Cox						
PROPOSALS.)	8. Well Number #1						
1. Type of Well: Oil Well Gas Well Other							
2. Name of Operator	9. OGRID Number 236378						
Saber Resources LLC							
3. Address of Operator	10. Pool name or Wildcat						
400 W Illinois, Suite 950, Midland, Texas 79701	Knowles; Devonian South						
4. Well Location							
Unit Letter F : 1980 feet from the North line and	1980feet from theWestline						
Section 13 Township 17S Range 38E							
11. Elevation (Show whether DR, RKB, RT, GR, etc.							
3685' GL	Antonia and the second second						
Pit or Below-grade Tank Application 🗌 or Closure 🗌							
Pit typeDepth to GroundwaterDistance from nearest fresh water wellD	istance from nearest surface water						
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls;	1						
12. Check Appropriate Box to Indicate Nature of Notice							
PULL OR ALTER CASING DIMULTIPLE COMPL CASING/CEME	NT JOB						
13 Describe proposed or completed operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date						
of starting any proposed work). SEE RUTHE OIL FCONSERVATION D	wach wellbore diagram of proposed completion						
or recompletion. BE NOTIFIED 24 HOURS PI	SIGR TO THE						
	ODEDATIONS						
Saber Resources proposes to P&A the subject we BEGINNING OF PLUGGING							
1 - Set  5 - 1/2" CIBP (a) $12,020' - cap  w/35'$ of cement							
2 – Load the hole with 10#/gals plug mud 3 – Pump 35 sxs cement from 9100' to 9000'							
4 - Pump 35 sxs cement from 6100' to 6000'							
5 - Pump 50 sxs cement from 5065' to 4900' (WOC & Tag)							
6 – Pump 35 sxs cement from 2000' to 1900'							
7 – Pump 35 sxs cement from 410' to 310' (WOC & Tag)	S. A.V.						
8 – Pump 10 sxs cement from surface pulg	10 m 15 m						
Cut off wellhead and dead men anchors. Install 4" dry hole marker, clear & clean off loc	ation. File all necessary NMOCD paperwork.						
P&A will commence as soon as a pulling unit is available.							
I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	lge and belief. I further certify that any pit or below-						
grade tank has been win be constructed of closed according to MNOCD guidennes El, a general per mer							
SIGNATURE SIGNATURE TITLE	DATE 5/7/67						
	71						
Type or print name: Douglas Keathley E-mail address: doug@saberresources.com	Telephone No. 432-685-0169						
For State Use Only OC FIELD REPRESENTATIVE II/3							
APPROVED BY LU. Wink	DATE						
Conditions of Approval (if any): GARY WWINK							

OC FIELD	REPRESENTATIVE II/STAFF MANAGER



	<u>,                                     </u>				1 - 130	30' FNL	& 1980	' FWL o	f Sec. 1	I3, T-17	S, R-38	E, Un	it Lette	er "F"				
													1					
			22	282			10 sxs	cement f	or surfac	e plug								_
Spud:	10/20/7	9	骸胶	2 4		<u> </u>	15'	' Hole Siz										-
Compl	: 2/1/80			Ř – –			<b>4</b>	HOIE SIZ		-				+ +				
Compi	. 2/1/00		40	å – – – – – – – – – – – – – – – – – – –		8 C -												
TA'ed:	9/91					<u> </u>												
		195		006777	12 N	Ø 10												
										casing								
				a Star Star		3				ith 450 s	sxs - cir	c'd						
			88	§	<u> </u>	35	sxs cen	nent 410'	- 310'							_		
	3685' G 3700 ' K					8——	+					_				-		
ELEV:	<u>3/00 R</u>	.D	10 2	Annema	. 8	<b>3</b>	+											-
API # 3	30-025-2	6494		1000		25		-										;
						35	sxs cer	nent 2000	' - 1900'									
						â						_						
			1219			§												
			彩纹	å		\$ <u> </u>											-	
				-		(6/05)	Casing	leak 2997	' - 3030'	squz w/	410 sxs	cmt circ	'd 20 bb	is to su	urf			
<u> </u>		<u> </u>	2	4		&——						_					+	
	<u> </u>	$\vdash$				8 – –						++			_			
		⊢— —	- <b>1</b>		<b>└──</b> ┃	€ 	11 1/4'	Hole							+		++	_
		<u>└─</u> ┤──				<u>s</u>		+		+							+	
		<u> </u>	- X				+											
1					<u>⊢ I – I</u> ?	2												
	+ + - +			Social Section 2	- X	2												
							8 !	5/8" - 24#	& 32# (	asing @	₱ 5017'							1
	+			19435				ment w/				face						-
		<u> </u>				50 ext	1	t @ 5065'										
				<b>a</b>		(11/91	) Locate	d casing	leak @ !	5809' to 5	5874' - so	zd w/ 1	50 sxs					
		,	10	ĝ 👘	1	(11/05	) Locate	hole in c	asing @	5919' so	juz w/ 15	0 sxs ci	nt					
	-			2.67								-						
				2833	200 EX	- 35 sxs	s cemen	t @ 6100'	- 6000'			_	-i-i-				-	
		<b> </b>	$\downarrow$											_				
			- 22	<u>.</u>					_						_		+	
			<b>i</b> @			(11/05	) Locate	e Casing I	eak 7303	5' - 7335'	squz w/	150 sxs					+	· ·
			i															
↓ Ì	+	<b>↓↓</b>			-		<u> </u>											
ļļ	+										01							_
·	+		<b>-</b>	×	<b>- 97</b> 3	(5/05)	located	hole in c	asing 83	66 838	s -squz (	oπ w/ 59	DDIS CN	nt			$+$ $+$ $\cdot$	
+		/8" Hole	₽ <b>→</b>	0000000														
∔ <b></b> -+	+	$\vdash$						1 @ 0100!	0000'									
	+		<u> </u>	22 °C ?*** * *		35 SX8	s cemen	t @ 9100'	- 9000									
		$\vdash$	+	++		Calc'r		11,210										
	+	$\vdash$		e —	- 02			U 201 201 1	-									_
	+	+		4 K			+	+										
	+ + +	<u>                                     </u>	3	3						+								
+				S CONTRACTOR	3.2 19		+ +											
	+ +			2.0		CIBP	Set @ 1	2,020' - Ca	ap w/ 35'	of ceme	ent							
							ŢŢŢ										++	
						Ξ /1	2/79) Pe	rf: 12,120	- 12 134	15 ho	les							
	+	1 1	1 236	<b>M</b>		= (6	/05) Per	: 12,142'	12,147	(4 JSPF)	) + 12.12	2' - 12.1	32'					
							1/2" 17#	& 20# ca	sing @ 1	2,147'								
				N		5												- 1
							0 sxs ce	ement										
Origin	al TD @	12,168			}	25	i0 sxs ce											
Origin	al TD @	12,168				25	i0 sxs ce	ement n OH to '	12,220'									
Origin	al TD @	12,168				25	i0 sxs ce		12,220'									
Origin	al TD @	12,168				25	i0 sxs ce		12,220'									

.