Form 3160-5 (April 2004)

OCD-HOBBS

\mathbf{D}

UNITED STATES	
EPARTMENT OF THE INTERIOR	
UREAU OF LAND MANAGEMENT	

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

NΜ	1-062300	
6.	If Indian Allottee or Tribe Name	

232425262720

apandoned w	ell. Use Form 3160 - 3	(APD) for such pro	oposais.					
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well X Oil Well Gas Well Other				NM 70928 A 8. Well Name and No.				
Name of Operator Pogo Pro	oducing Company			Cotton 9. APIW	Draw Unit #75 ell No.			
3a Address 3b. Phone No. (include area code)				30-025-27873				
P. O. Box 10340, Mid	and, TX 79702	432-685-810	0	10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Paduca I	Delaware			
455' FNL & 1980' FWL, Section 15, T25S, R32E 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE					or Parish, State n'ty, NM COTHER DATA			
TYPE OF SUBMISSION			PE OF ACTION	- 				
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Stan Reclamation Recomplete Temporarily Ab	·	Water Shut-Off Well Integrity Other			

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

The Cotton Draw Unit #75 was a TA'd well when Pogo purchased the lease and took over operations in August 2005. In March 2007, Pogo drilled out the CIBP @ 4635' and attempted to return the well to production. Swab test results indicated the well capable of producing 40 to 50 bbls of water per hour with no oil or gas. A CIBP was reset at 4635' and the well was circulated with packer fluid. The casing and CIBP were tested to 500# for 30 minutes. The test was witnessed by BLM representative Jim McCormick. The well was again TA'd and remains on the NMOCD inactive well list.

			81920272	Palis	P33031-1	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	 			Sales.		
Cathy Wright	Title	Sr. Eng Tech	S.O.	, 4	0 ^{C7} /	
Signature Carly Whight	Date	04/16/07	ACCE	TED/FORS	- 1///	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by		Title	Date	MAY 3 20	07	
Conditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.		Office		SLEY W. INC		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person l within	knowingly and willfully to n	ake to any dep	PACEUM ENC partment or agency of	the United	

(Instructions on page 2)