State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATION DIV	ISION
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-34994
DISTRICT II		5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210		STATE FEE X
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		T. V. V. J. Heis A man art Name
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK	North Hobbs (G/SA) Unit sals.). Section 33
	PPLICATION FOR PERMIT" (Form C101) for such propo-	8. Well No. 631
1. Type of Well: Oil Well	Gas Well Other Water Injector	
2. Name of Operator	A Property of the second	9. OGRID No. 157984
Occidental Permian Ltd. 3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323	
4. Well Location		
Unit Letter B : 490	Feet From The North 232	25 Feet From The East Line
Section 33	Township 18-S Rang	ge 38-E NMPM Lea County
Section 33	11. Elevation (Show whether DF, RKB, RT GR, etc.)	
English Committee Committe	3642'	
Pit or Below-grade Tank Application	or Closure	
Pit Type Depth of Ground	d Water Distance from nearest fresh water	er well Distance from nearest surface water
Pit Liner Thickness mil	Below-Grade Tank: Volumebbls; Cor	
	S I I I NA SENAL	Deposit on Other Date
12. Check	Appropriate Box to Indicate Nature of Notice,	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE D	DRILLING OPNS. PLUG & ABANDONMENT
	CHANGE PLANS COMMENCE D	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS COMMENCE D Multiple Completion CASING TEST OTHER:	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS COMMENCE D Multiple Completion CASING TEST OTHER:	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS COMMENCE D Multiple Completion CASING TEST OTHER: Decrations (Clearly state all pertinent details, and give	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103.	CHANGE PLANS Multiple Completion CASING TEST OTHER: Decrations (Clearly state all pertinent details, and give For Multiple Completions: Attach wellbore diagram	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007	CHANGE PLANS Multiple Completion CASING TEST OTHER: Decrations (Clearly state all pertinent details, and give For Multiple Completions: Attach wellbore diagram	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes	CHANGE PLANS Multiple Completion CASING TEST OTHER: Decrations (Clearly state all pertinent details, and give For Multiple Completions: Attach wellbore diagram	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI;	CHANGE PLANS Multiple Completion CASING TEST OTHER: Decrations (Clearly state all pertinent details, and give For Multiple Completions: Attach wellbore diagram	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes	CHANGE PLANS Multiple Completion CASING TEST OTHER: Decrations (Clearly state all pertinent details, and give For Multiple Completions: Attach wellbore diagram	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes	CHANGE PLANS Multiple Completion CASING TEST OTHER: Decrations (Clearly state all pertinent details, and give For Multiple Completions: Attach wellbore diagram	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI	ORILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give of the perations) For Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief.	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test pertinent dates, including estimated date of starting any of proposed completion or recompletion. If with the certify that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give of the perations) For Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief.	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test pertinent dates, including estimated date of starting any of proposed completion or recompletion.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give) For Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief. a general permit or an (attach plan)	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test pertinent dates, including estimated date of starting any of proposed completion or recompletion. If with the certify that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Or proposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give perations) For Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief. Title Acceptable Title Acceptable Title Acceptable COMMENCE Decomplete Decomple	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test pertinent dates, including estimated date of starting any of proposed completion or recompletion. Ifurther certify that any pit or below-grade tank has been/will be need) alternative OCD-approved
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE MANAGEMENT SIGNATURE	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give of the Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief. Titue and complete to the best of my knowledge and belief. TITLE Actions of the Multiple Completion of the Mul	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any of proposed completion or recompletion. If the pertinent dates, including estimated date of starting any of proposed completion or recompletion. If the pertinent dates, including estimated date of starting any of proposed completion or recompletion. If the pertinent dates, including estimated date of starting any of proposed completion or recompletion. If the pertinent dates, including estimated date of starting any of proposed completion or recompletion. If the pertinent dates, including estimated date of starting any of proposed completion or recompletion.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Or proposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. J	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give of the Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief. Titue and complete to the best of my knowledge and belief. TITLE Actions of the Multiple Completion of the Mul	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test pertinent dates, including estimated date of starting any of proposed completion or recompletion. If with the certify that any pit or below-grade tank has been/will be need) alternative OCD-approved dministrative Associate DATE 05/07/2007 SON@OXY.COM TELEPHONE NO. 806-592-6280
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Or proposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. J	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give of the Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief. Titue and complete to the best of my knowledge and belief. TITLE Actions of the Multiple Completion of the Mul	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test Pertinent dates, including estimated date of starting any of proposed completion or recompletion. If our there certify that any pit or below-grade tank has been/will be need) alternative OCD-approved dministrative Associate DATE O5/07/2007 SON@OXY.COM TELEPHONE NO. 806-592-6280
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Or proposed work) SEE RULE 1103. Test Date: 04/27/2007 Pressure Reading: Initial – 440 PSI; Length of pressure test: 30 minutes Witnessed: NO I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. J For State Use Only APPROVED BY	CHANGE PLANS Multiple Completion CASING TEST OTHER: Perations (Clearly state all pertinent details, and give of the Multiple Completions: Attach wellbore diagram 15 min – 440 PSI; 30 min – 440 PSI true and complete to the best of my knowledge and belief. Titue and complete to the best of my knowledge and belief. TITLE Actions of the Multiple Completion of the Mul	PRILLING OPNS. PLUG & ABANDONMENT AND CEMENT JOB MIT test pertinent dates, including estimated date of starting any of proposed completion or recompletion. If with the certify that any pit or below-grade tank has been/will be need) alternative OCD-approved dministrative Associate DATE 05/07/2007 SON@OXY.COM TELEPHONE NO. 806-592-6280

