

Submit 3 Copies To Appropriate District Office

**District I**

1625 N. French Dr., Hobbs, NM 88240

**District II**

1301 W. Grand Ave., Artesia, NM 88210

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410

**District IV**

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
March 4, 2004

WELL API NO.

30-025-02948

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Central Vacuum Unit

8. Well Number

#4

9. OGRID Number

10. Pool name or Wildcat

Vacuum Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Chevron USA Inc.

3. Address of Operator

11111 S. Wilcrest, Houston, Tx 77099

4. Well Location

Section 30

660 feet from the North line and 660 feet from the West line

Township 17-S

Range 35-E

NMPM Lea

County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL D Sect 30 Twp 17S Rng 35E Pit type Steel Depth to Groundwater Distance from nearest fresh water well

Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;

660 feet from the North line and 660 feet from the East line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD prior to MI & RU P & A Equip 5/3/07
2. Set 5 1/2 CIBP @ 4133 5/4/07
3. Spot 25 sx class c cmt 4133-3900 5/7/07
4. Perf @ 2800' squeezed 60 sx class c cmt 5/7/07 tag @ 2400' 5/8/07.
5. Perf @ 1700' squeezed 75 sx class c cmt 5/8/07 tag @ 1363' 5/9/07
6. Perf @ 250, circ 60 sx class c cmt tag & Surface 5/9/07
7. Install dry hole marker 5/9/07.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

TITLE

Consultant

DATE 5/9/07

Type or print name

Jimmy Bagley

E-mail address:

Telephone No. 432-561-8600

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

MAY 16 2007