
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South S	St. Francis Dr. NM 87505	WELL API NO. 30-025-05493
DISTRICT II	,		5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210			STATE X FEE
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410			
SUNDRY NOT	ICES AND REPORTS ON WEI	LLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G101) for such proposals.)			Section 25
1. Type of Well:			8. Well No. 744
Oil Well X	Gas Well Other Ter	mporarily Abandoned	0.00ND N
2. Name of Operator			9. OGRID No. 157984
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323		110000 (3,011)
4. Well Location			
Unit Letter P : 330 Feet From The South 330 Feet From The East Line			
Section 25	Township 18-S	Range 37-E	NMPM Lea County
	11. Elevation (Show whether DF, RK 3661' RKB	B, RT GR, etc.)	
D' Di La La La Talanda			
Pit or Below-grade Tank Application or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
Oh all Assessing Day to Indicate Nature - (Nation Day on Other Date			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN	IS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	
OTHER:		OTHER: Temporarily	Abandon Well X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
1. RUPU & RU. 2. RU wireline & perforate the & 4126'. RD wireline. This Approval of Temporary.			
3. Kill well. ND wellhead/NU BOP. 4. POOH & lay down ESP equipment. 5. P.H. wireling & P.H. w/CIBP set @4217' Dump 10' of cement on CIBP. RD wireling.			
3. Kill well. ND wellhead/NU BOP. 4. POOH & lay down ESP equipment. 5. RU wireline & RIH w/CIBP set @4217'. Dump 10' of cement on CIBP. RD wireline. 6. ND BOP/NU wellhead.			
6. ND BOP/NU wellhead. 7. Test casing to 540# for 30 minutes and chart for the NMOCD.			
7. Test casing to 540# for 30 minutes and chart for the NMOCD.			
8. RDPU & RU. Clean location.			
W 11 4 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	,	RUPU 05/03/2007 RDPU	05/04/2007
Well is temporarily abandoned.			
I hereby certify that the information above is t	rue and complete to the hest of my know	ledge and belief I further certify	hat any pit or below-grade tank has been/will be
constructed or		-	
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved
		_ plan	
SIGNATURE / MLholy	- (JADHMOW	TITLE Administrative	Associate DATE 05/09/2007
TYPE OR PRINT NAME Mendy A. Jo	hnson E-mail address:	mendy johnson@oxy.com	TELEPHONE NO. 806-592-6280
For State Use Only			
APPROVED BY Hay W	Wink	TITLE	DATE
CONDITIONS OF APPROVAL MANY: OC FIELD REPRESENTATIVE IL/STAFF MANAGER			
V	•		WOIAFF MANAGER
MAY 1 6 2007			
			~ 1 0 2001



LARRY # 25 THRECONDER

LARRY # 25 TH RECONDER

NHU TRUCKING

PATE # 12517

PATE # 12517

CALIBRATED

CALIBRATED

UNIT