

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
OCD-HOBBS

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NM 14332 103635
2. Name of Operator KAISER FRANCIS OIL COMPANY		6. If Indian, Allottee or Tribe Name -
3a. Address P.O. Box 21468, Tulsa, OK 74121-1468	3b. Phone No. (include area code) 918-491-4314	7. If Unit or CA/Agreement, Name and/or No. NNM 94500
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SE NE (1980' ENL & 660' FEL) Sec. 6-22S - 32E		8. Well Name and No. FEDERAL CK COM #1
		9. API Well No. 30-025-27473
		10. Field and Pool, or Exploratory Area W. BILBRAY (Atoka)
		11. County or Parish, State LEA, NM


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Charge Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

2-22-07 M.I.R.U. 2-23-07 Run 2 3/8 CIBP & set @13,577'. Attempt to test tbg. No test. 2-23-07 Cut tbg. off @13,555'. 2-26-07 P.O.O.H. w/tbg. Laydown bad tbg. w/holes. 2-27-07 Rig tbg. tester & test bottom 112 joints. Run tbg. to 13,555' & circ. hole w/10# M.L.F. 2-28-07 Spot 25 sx. cmt. on top of tbg. Stub inside of 4 1/2" liner & circ. TOC @13,204'. 2-28-07 Pull tbg. to 12,039'. Spot 25 sx. cmt. Cacl TOC @11,690'. Pull tbg. to 11,465'-4 1/2" line. Top @11,365'. Mix & spot 50 sx. cmt. WOC. 3-1-07 Tag TOC @11,293 72' above liner top. 3-1-07 Tbg. plugged. Cut & leave plugged tbg. in hole 10 jts. Pull tbg. to 8,529'. Mix & spot 50 sx. cmt. Tag @8,396'. Pull tbg. to 6,500'. Mix & spot 50 sx. class cmt. Pull tbg. to 4,640'. Mix & spot 50 sx. cmt. - WOC. 3-2-07 Rig up 7 5/8". Cut on wireline again in hole. Tag TOC @4,380'. 3-2-07 Cut 7 5/8" csg. @4,015'. 3-5-07 Pull & lay down 7 5/8" csg. 3-6-07. T.I. w/tbg. to 4,100'. Mix & spot 80 sx. cmt. Circ. TOC @3,857'. Pull tbg. to 2,000'. Spot 60 sx. cmt. Cacl TOC @1,854'. Pull tbg. to 608'. Spot 100 sx. cmt. W.O.C. & tag @462'. Respot 25 sx. cmt. W.O.C. 3-7-07 Test TOC @398'. Spot 25 sx. surface. Plug 50' to surface.

R.D. M.O.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) RANDALL MINEAR		Title P & A Supv.
Signature 		Date 4-25-07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by /s/ James A. Amos	Title	Date 4-25-07
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.